



Document 2026 GW2614

Book 2026 Page 2614 Pages 10

Date 9/01/2026 Time 12:51:56PM

Rec Amt \$.00

BRANDY MACUMBER, COUNTY RECORDER
MADISON COUNTY IOWA

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT
TO BE COMPLETED IN FULL BY TRANSFEROR

If the transaction is exempt from filing a declaration of value pursuant to Iowa Code 428A.1(2), **STOP HERE**. Pursuant to Iowa Code section 558.69(1), when no declaration of value is submitted during a transaction, you are not required to submit a groundwater hazard statement or include the statutory language in Iowa Code section 558.69(8A). Please consult your realtor or legal counsel for further advice, including on whether a declaration of value is required. The Department provides this information for statutory reference only.

Instructions for this document can be found at:

<https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960%20Instructions.pdf>

Attachment 1, if required, can be found at: <https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960a.pdf>

TRANSFEROR:

Name M. Randall Townsend and Kimberly A. Townsend

Address 715 S 8th Ave Winterset, IA 50273

Number and Street or RR

City, Town or PO

State

Zip

TRANSFeree:

Name Nathan and Emily Kuhns

Address 2230 260th Street, Winterset, IA 50273

Number and Street or RR

City, Town or PO

State

Zip

Address of Property Transferred:

2230 260th Street, Winterset, IA 50273

Number and Street or RR

City, Town or PO

State

Zip

Legal Description of Property: (Attach if necessary)

See attached.

1. Wells (check one)



No Condition - There are no known wells situated on this property.

Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)



No Condition - There is no known solid waste disposal site on this property.

Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- ☒ No Condition - There is no known hazardous waste on this property.
- ☐ Condition Present - There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- ☒ No Condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

- ☒ No Condition - There are no known private burial sites on this property.
- ☐ Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

- ☐ No Condition - All buildings on this property are served by a public or semi-public sewage disposal system.
- ☐ No Condition - This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
- ☒ Condition Present - There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #7]
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. This property is exempt from the private sewage disposal inspection requirements pursuant to the following
Exemption [Note: for exemption #7 use prior check box]: _____
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The private sewage disposal system has been installed within the past two years pursuant to permit number:

Review the following two directions carefully:

- A. If you selected a box stating "No Condition" for every numbered section above, **STOP HERE**. Do not submit this form. Instead, pursuant to Iowa Code section 558.69(8A), you must include the following language on the first page of the recorded deed, instrument, or other writing:

"There is no known private burial site, well, solid waste disposal site, underground storage tank, hazardous waste, or private sewage disposal system on the property as described in Iowa Code section 558.69, and therefore the transaction is exempt from the requirement to submit a groundwater hazard statement."


Please consult your realtor or legal counsel for further advice on this exemption. By law, the owner of the property is responsible for the accuracy of this statement, and the Department provides this information for statutory reference only.

- B. If you checked any box stating "Condition Present" for any of the numbered sections above, continue below. You must complete this form, including providing all required information, and you must submit this form to the county recorder's office with declaration of value.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature:


(Transferor or Agent)

Telephone No.:

515-250-1425

Legal Description

The West Half($\frac{1}{2}$) of the Northeast Quarter($\frac{1}{4}$) of the Northwest Quarter ($\frac{1}{4}$) of Section Thirty (30), Township Seventy-five (75) North, Range Twenty-seven (27) West of the 5th P.M., Madison County, Iowa

062-26
30 - Scott



IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLDS
LT. GOVERNOR CHRIS COUNOYER

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 22912 JAMES SULLIVAN CERT # 13653

Site Information

Parcel Description: **REVISED, Madison County, 30-75-27**

Address: **2230 260th St., Winterset, IA 50273**

County: **Madison**

Owner Information

Property is owned by a business: **No**

Business Name:

Owner Name: **Randall Townsend**

Email Address: **myrontownsend50@gmail.com**

Address: **715 S. 8th Ave., Winterset, IA 50273**

Phone No: **515-250-1425**

Site related information

No Of Bedrooms: **3**

Facility Type: **Residential**

Last Occupied: **01/01/2026**

Permit issued by County: **Yes**

All plumbing fixtures enter septic system: **Yes**

Property Information Comments:

Inspection Date: **08/17/2026**

Currently Occupied: **No**

System Installation Date: **11/20/2012**

Permit Number: **048-12**

County contacted for records: **Yes**

Primary Treatment

Septic Tank

Tank Name: **Septic Tank**

Tank Material: **Concrete**

No. of Compartments: **2**

Date Pumped: **8/17/2026**

Distance To Well (Ft.):

Risers Intact: **Yes**

Type: **Septic Tank**

Tank Corrosion Type: **None**

Pump Tank Chamber: **No**

Meets Setback to Well: **N/A**

Is Accessible: **Yes**

Effluent Filter Present: **Yes**

Tank Size (Gal): **1500**

Liquid Level Type: **Normal**

Licensed Pumper Name: **DPS**

Well Type:

Lid Intact: **Yes**

Watertight: **Yes**

Tank/Vault Pumped: **Yes**

Inlet Baffle Present: **Yes**

Outlet Baffle Present: **Yes**

Functioning as Designed: **Yes**

Tank Comments:

General Primary Treatment Comments:

Distribution Type

Distribution Box

Label: **Distribution Box**

Material Type: **Plastic**

Accessible: **Yes**

Box Opened: **Yes**

Baffle Present: **Yes**

Speed Levelers Present: **Yes**

Watertight: **Yes**

Functioning As Designed: **Yes**

General Distribution System Comments :

Secondary Treatment

Sand Filter

Filter Type: **Subsurface**

Distribution Type: **Distribution Box**

Material Type: **Rock and PVC Pipe**

Absorption Area: **720**

System Hydraulic Loaded: **Yes**

Gallons Loaded: **400**

Discharge At Time of Inspection: **Yes**

CBOD5 Results: **8**

TSS Results: **4**

Disinfection Present: **No**

Disinfection Type:

Tertiary Treatment Present: **No**

Tertiary Treatment Type:

Meets Setback to Well: **N/A**

Well Type:

Distance To Well (Ft.):

Sand Filter Probed: **Yes**

Vent(s) Located: **Yes**

Saturation or Ponding Present: **No**

Grass Cover Over System: **Yes**

Outlet Found: **Yes**

Sample Taken: **Yes**

GP4 Permitted: **No**

GP4 Required: **No**

System Located on Owner Property: **Yes**

Easement Present: **N/A**

Functioning as Designed: **Yes**

Comments:

General Secondary Treatment Comments:

Narrative Report

TOT Inspection Report Overall Narrative Comments: **The septic line leaves the house and head West to the septic tank. The septic tank is a 1500 gallon, concrete lister tank. The septic tank contains an influent, effluent, and center wall baffle as well as an effluent filter. The septic tank is watertight and functioning as designed at the time of the inspection. After the septic tank it enters the distribution box. The dbox contains all necessary speed levelers, as well as an influent baffle. The dbox is watertight and functioning as designed at the time of the inspection. After the dbox, it enters the 720 square foot sand filter. The sand filter was probed, and no saturation or ponding is present. The sand filter is functioning as designed at the time of the inspection. After the sand filter, it runs west to the trees and discharges.**

TIME OF TRANSFER INSPECTION TOT# 22912 JAMES SULLIVAN CERT # 13653

Owner Name: **Randall Townsend**

Address: **2230 260th St. , Winterset , IA 50273**


County: **Madison**

Inspection Date: **08/17/2026**

Submitted Date: **8/20/2026**

This page certifies a Time of Transfer Inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).

As-built Diagrams



[illegible]

Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. Please refer to the NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

- About the Inspection:** A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. **For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms.** This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. **This shall not be construed as a 90-day warranty.** There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.
- Treatment Recommendation Guidelines Regarding Subterranean Termites:** Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented and evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company.
For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on actions and or treatment.
- Obstructions and Inaccessible Areas:** No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.
- Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects.** Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.
- Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.**