



Book 2022 Page 3539


Document 2022 3539 Type 06 010 Pages 1
Date 12/01/2022 Time 1:12:34PM
Rec Amt \$7.00

Daneen Schindler, RECORDER/REGISTRAR
DELAWARE COUNTY IOWA

Prepared by: Fehr Graham, 221 East Main Street, Suite 301, Manchester, Iowa 52057 - Ph 563.927.2060

Project No. 22-299

Page SD-1

	<p>I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.</p> <p><u>Adam J. Recker</u> Adam J. Recker, P.L.S. License Number 24627 My license renewal date is December 31, 2023. Pages covered by this seal: SD-1</p> <p style="text-align: right;"><u>12-1-2022</u> Date</p>
---	---


State of Iowa)

ss.

County of Delaware)

Subscribed and sworn to before me by Adam J. Recker this 1st day of December, 2022.

[Signature]
Notary Public



SURVEYOR'S AFFIDAVIT

I, Adam J. Recker, Licensed Professional Land Surveyor in the State of Iowa, Number 24627, being first duly sworn, depose and state;

1. That I am a Licensed Professional Land Surveyor in the State of Iowa and have been at all relevant times;
2. That I prepared a plat of survey for Parcel 2022-46 and Parcel 2022-47 in the Northeast Quarter of the Southwest Quarter of Section 26, Township 88 North, Range 3 West of the 5th P.M., Delaware County, Iowa, which was filed for record on April 26, 2022, in Book 2022, Page 1323 in the Delaware County Recorder's Office, Manchester, Iowa;
3. And that on Sheet Number: 2 of 2 of the Plat is where it states for a Corner Monument Label "SW Corner NE1/4-SW1/4 SEC. 26-88-3 SET 1/2" Ø REBAR W/2" Ø ALUM CAP #24627" should read "SE CORNER NE1/4-SW SEC. 26-88-3 SET 1/2" Ø REBAR W/2" Ø ALUM CAP #24627" because the corner was incorrectly labeled.