Recorded: 5/10/2022 at 3:55:49.0 PM

County Recording Fee: \$0.00 lowa E-Filing Fee: \$0.00 Combined Fee: \$0.00

Revenue Tax:

Delaware County, Iowa Daneen Schindler RECORDER

BK: 2022 PG: 1497

# REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT TO BE COMPLETED BY TRANSFEROR

	ANSFEROR:	nce ? Carr	y Bern	4		
Ad	dress 13 27	Skony Sk and Street or FRR	City, To	Boone win or P.O.	TA State	50036 zp
TR Na	ANSFEREE:	5 Breckens	tedt			
Ad	dress 27(0)	217 K	St G	etlyille	TA State	52041
Ad	dress of Property	Transferred:				
	Number a	and Street or RR	City,	Town, or P.O.	State	Zlp
1.	☐ There is a we	known wells situated Il or wells situated or	this property	The type(s), loca	ation(s) and legal	status are
_		or set forth on an att	ached separa	ite sheet, as neces	ssary.	
2.		p <b>osal (check one)</b> nown solid waste dis	nocal site on t	thic proporty		
	☐ There is a soll Attachment #	id waste disposal site 1, attached to this de	e on this prop		on related thereto	is provided in
3.	Hazardous Wast			<b>-</b>		
	☐ There is haza	nown hazardous was rdous waste on this <sub>l</sub> 11, attached to this do	property and i		thereto is provid	ed in
4.	<b>Ungerground Sta</b>	orage Tanks (check	cone)			
	There are no small farm an instructions.)	known underground ad residential motor fo	storage tanks uel tanks, mo	on this property. st heating oil tanks	(Note exclusions , cisterns and se	such as ptic tanks, in
	☐ There is an ur	nderground storage t	ank on this pr	operty. The type(	s), size(s) and an	y known

substance(s) contained are listed below or on an attached separate sheet, as necessary.

5.		vate Burial Site (check one)
		There are no known private burial sites on this property.
		There is a private burial site on this property. The location(s) of the site(s) and known
		identifying information of the decedent(s) is stated below or on an attached separate sheet, as
_	<b>.</b>	necessary.
Ь.	Pn	yate Sewage Disposal System (check one)
	_	All buildings on this property are served by a public or semi-public sewage disposal system.
		This transaction does not involve the transfer of any building which has or is required by law to
		have a sewage disposal system.
	M	There is a building served by private sewage disposal system on this property or a building
		without any lawful sewage disposal system. A certified inspector's report is attached which
		documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A
		certified inspection report must be accompanied by this form when recording.
		There is a building served by private sewage disposal system on this property. Weather or
	_	other temporary physical conditions prevent the certified inspection of the private sewage
		disposal system from being conducted. The buyer has executed a binding acknowledgment
		with the county board of health to conduct a certified inspection of the private sewage disposal
		system at the earliest practicable time and to be responsible for any required modifications to
		the private sewage disposal system as identified by the certified inspection. A copy of the
		binding acknowledgment is attached to this form.
		There is a building served by private sewage disposal system on this property. The buyer has
		executed a binding acknowledgment with the county board of health to install a new private
		sewage disposal system on this property within an agreed upon time period. A copy of the
		binding acknowledgment is provided with this form.
	u	There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The
		buyer has executed a binding acknowledgment with the county board of health to demolish the
		building within an agreed upon time period. A copy of the binding acknowledgment is provided
		with this form. [Exemption #9]
		This property is exempt from the private sewage disposal inspection requirements pursuant to
		the following exemption [Note: for exemption #9 use prior check box]:
		The private sewage disposal system has been installed within the past two years pursuant to
		permit number
Inf	A PTW	ation required by statements checked above should be provided here or on separate
eh/	ete	attached hereto:
911	904	
_		
	•	
		I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS
		FORM
		AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
Sia	nati	Telephone No.: ()
~.8		(Transferor & Agent)

GOVERNOR KIM REYNOLDS LT. GOVERNOR ADAM GREGG

DIRECTOR KAYLA LYON

## TIME OF TRANSFER INSPECTION TOT# 172 ROGER GROTH CERT # 8813

Site Information

Parcel Description: 220290100609

Address: 23119 263rd St., Delhi, IA 52223

County: Delaware

Owner Information

Property is owned by a business: No

**Business Name:** 

Owner Name: Lance & Carry Berry

Email Address: berryl1000@hotmail.com

Address: 1327 Story Street Apt. 4, Boone, IA 50036

Phone No: 515-778-3403

-Site related information -

No Of Bedrooms: 1 Inspection Date: 04/22/2022

Facility Type: Other Currently Occupied: No

Last Occupied: System Installation Date: 09/15/2014

Permit issued by County: Yes Permit Number: 2312

All plumbing fixtures enter septic system: Yes County contacted for records: Yes

**Property Information Comments:** 

This is 1 of three systems for the Rocky Nook Association. This is called the West System. This is a seasonal cabin.

#### -Primary-Treatment-

#### Tank 1 Septic tank

Tank Name: Tank 1 Septic tank Type: Septic Tank Tank Size (Gal): 6,000

Tank Material: Concrete Tank Corrosion Type: None Liquid Level Type: Normal

No. of Compartments: 2 Pump Tank Chamber: No Licensed Pumper Name: Groth Services

LIC

Date Pumped: 8/30/2019 Meets Setback to Well: Yes Well Type: Private

Distance To Well (Ft.): >100' Is Accessible: Yes Lid Intact: Yes

Risers Intact: Yes Effluent Filter Present: Yes Watertight: Yes

Tank/Vault Pumped: Yes

Inlet Baffle Present: Yes

Outlet Baffle Present: Yes

Functioning as Designed: Yes

**Tank Comments:** 

Tank 2

Tank Name: Tank 2

Type: Septic Tank

Tank Size (Gal): 2,000

Tank Material: Concrete

Tank Corrosion Type: None

Liquid Level Type: Normal

No. of Compartments: 2

Pump Tank Chamber: No

Licensed Pumper Name: Groth Services

LLC

Date Pumped: 8/30/2019

Meets Setback to Well: Yes

Well Type: Private

Distance To Well (Ft.): >100'

Is Accessible: Yes

Lid Intact: Yes

Risers Intact: Yes

**Effluent Filter Present** 

Watertight: Yes

Tank/Vault Pumped: Yes

Inlet Baffle Present: Yes

Outlet Baffle Present No

Functioning as Designed: Yes

Tank Comments: Treatment tank for the Orenco dual filter pod system.

**General Primary Treatment Comments:** 

Distribution Type

**Header Pipe 1** 

Label: Header Pipe 1

Material Type : Plastic

Accessible: No

Functioning As Designed: Yes

General Distribution System Comments: Header pipe feeds 2 laterals in a large tertiary system (10'x30' rock & pipe with above wet grade, vent/outlet which is dry.

Secondary Treatment

**Pkg Treatment Media Filter1** 

Media Type: Textile

Manufacturer: Orenco

Model Number: Dual AX20 pods

Serial Number: RTU #130109

11.0 11.100100

Maintenance Contract: Yes

System Located on Owner Property: Yes Easement Present: N/A

Maintenance Provider: Oasis
System Hydraulic Loaded: No

Gallons Loaded:

Discharge At Time of Inspection: No

CBOD Results (mg/L):

TSS Results (mg/L):

DisInfection Present: No

Disinfection Type:

Tertiary Treatment Present: Yes

Tertiary Treatment Type: Soil

**Absorption Field** 

Meets Setback to Well: Yes

Well Type: Private

Distance To Well (Ft): >100'

**GP4 Permitted:** 

GP4 Required:

Vent(s) Present: Yes

ar rioquirou.

Sample Taken: No

Media Present: Yes

Outlet Found: Yes

Functioning as Designed: Yes

Comments:

General Secondary Treatment Comments: Outlet vent pipe was dry with no signs of ever being wet.

#### Narrative Report

Tot Inspection Report Overall Narrative Comments: This is a 1 Bedroom seasonal cabin on Lake Delhi in the Rocky Nook camp. This is one of three cluster systems for the Rocky Nook Association, WEST system. There are 10 connections, including the shower house. The 6000 gal. dual compartment septic tank looked good with very low solid content. The 2000 gal. dual compartment secondary treatment tank looked good with very low solid content. Both septic tank and treatment tank were pumped by Groth Services LLC on 08/30/2019. Orenco AX20 filter pods looked normal. The Vericomm control panel checked out good. The treated effluent leaves the recirculation valve to a single header pipe, splits to 2 perforated pvc pipes in a rock and pipe, large tertiary absorption system with an above set grade vent/outlet pipe. Outlet was dry with no signs of ever being wet.

DIRECTOR KAYLA LYON

### TIME OF TRANSFER INSPECTION TOT# 172 ROGER GROTH CERT # 8813

Owner Name:

**Lance & Carry Berry** 

Address:

23119 263rd St., Delhi, IA 52223

County:

**Delaware** 

Inspection Date:


04/22/2022


**Submitted Date:** 


04/27/2022


This page certifies a Time of Transfer inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).


4/27/2022 6:30:36 PM



















# GROTH SERVICES

# TIME OF TRANSFER INSPECTION MAP

DATE 4-22-22 SELLER Lance + Corry Benglover
ADDRESS 23119=263" CTY Delhi, IA.

		· .
		• •
out Apres and pay to be supported.	, m + m	10'x30' rock kpip
A		. Tertiniza absorpti
7	_2,000 ged	<b>X</b> ————————————————————————————————————
	Treatment 6	<b>7</b>
<b>(N)</b>	Tank.	2. Ax20 Vent/ove
Leps	so gali pro	7 Filter Ppds
	SO. gal.	Cabi 25137
of Manuforsing was very as a second manuform of the second	and the second s	and the second s
St. No. 1 year congress accepts a seek of update of the property street of		A STATE OF THE STA
A was an analysis of the state		Cabo 23128
Cal. 23/19	and the second second	والمرافق والمعارض والمعارض والمتحارض
anners of external or makes are also as a description of the second of t	V872	and the state of t
Cabin 23111		regular called an extra group absorber and administrative control of the called an extra group absorber and administrative control of the called an extra group absorber and administrative control of the called an extra group absorber and administrative control of the called an extra group absorber and administrative control of the called an extra group and administrative control of the called and administrative control
Appropriate property and a second of the contract of the contr	eretare ()	and the second s
Both house		and the property of the second
Canix 23/05		and a proper for an all the state of the sta
the describing screen versus anders are included as in the		the second of th
A the state of the	And the second second second	age of the state o
Cobin 22099		The second section of the second section secti
com Diose		and a gradual control of the control
المنظمة المنظمة المنظمة والمنظمة المنظمة المنظمة المنظمة المنظمة المنظمة المنظمة المنظمة المنظمة المنظمة المنظ - المنظمة المن	and the second s	a management of the state of th
. Cabin 23049	and planner and a second of a	ngga san nagan ana ay ini na nagang nagang nagang nagang na na nagang na na nagang An
Casin 33 177	Care Care Care Care Care Care Care Care	And the second s
tara matembran kanangan saga Tangan kanangan dan kanangan mengan	univeral in the medical consistency in the contract of the con	Approximately for the first control of the control