

Document 2022 GWH-2632 Type 53 001 Pages 1: Date 9/02/2022 Time 9:54:12AM Rec Amt \$.00

Daneen Schindler, RECORDER/REGISTRAR DELAWARE COUNTY IOWA

#### **REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT**

TO BE COMPLETED BY TRANSFEROR

#### TRANSFEROR:

Name: Jennifer L. Wall and Dustin W. Wall

Address: 2145 235th Avenue, Manchester, IA 52057

TRANSFEREE:

Name: Peyton L. Kilburg and Ashleigh N. Kilburg Address: 8239 Ginger Court, Peosta, IA 52068

Address of Property Transferred:

2145 235th Avenue, Manchester, Iowa 52057

Legal Description of Property: (Attach if necessary)

Parcel 'J' Being Part Of The Southeast Quarter Of The Northwest Quarter (SE1/4-NW1/4) Of Section 32, Township 89 North, Range 4 West Of The Fifth Principal Meridian, Delaware County, Iowa, And Parcel 'K' Being Part Of The Southeast Quarter Of The Northwest Quarter (SE1/4-NW1/4) And Part Of The Northeast Quarter Of The Southwest Quarter (NE1/4-SW1/4) Of Section 32, Township 89 North, Range 4 West Of The Fifth Principal Meridian, City Of Delaware, Delaware County, Iowa, according to plat recorded in Book 2012, Page 884

#### 1. Wells (check one)

- ☐ There are no known wells situated on this property.
- There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

### 2. Solid Waste Disposal (check one)

- There is no known solid waste disposal site on this property.
- ☐ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

### 3. Hazardous Wastes (check one)

- There is no known hazardous waste on this property.
- ☐ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

#### 4. Underground Storage Tanks (check one)

- ☑ There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

#### 5. Private Burial Site (check one)

- There are no known private burial sites on this property.
- ☐ There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Priv	ate Sewage Disposal System (check one)
	All buildings on this property are served by a public or semi-public sewage disposal system.
	This transaction does not involve the transfer of any building which has or is required by law to have a
	sewage disposal system.
	There is a building served by private sewage disposal system on this property or a building without any lawful
	sewage disposal system. A certified inspector's report is attached which documents the condition of the
	private sewage disposal system and whether any modifications are required to conform to standards adopted
	by the Department of Natural Resources. A certified inspection report must be accompanied by this form
	when recording.
	There is a building served by private sewage disposal system on this property. Weather or other temporary
	physical conditions prevent the certified inspection of the private sewage disposal system from being
	conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a
	certified inspection of the private sewage disposal system at the earliest practicable time and to be
	responsible for any required modifications to the private sewage disposal system as identified by the certified
	inspection. A copy of the binding acknowledgment is attached to this form.
	There is a building served by private sewage disposal system on this property. The buyer has executed a
	binding acknowledgment with the county board of health to install a new private sewage disposal system on
	this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this
	form.
	There is a building served by private sewage disposal system on this property. The building to which the
	sewage disposal system is connected will be demolished without being occupied. The buyer has executed a
	binding acknowledgment with the county board of health to demolish the building within an agreed upon time
	period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to the following
	exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to permit number
	· · · · · · · · · · · · · · · · · · ·
•	
	tion required by statements checked above should be provided here or on separate sheets attached
hereto:	
	•
	A HEREBY REAL ARE THAT I HAVE BENJEWER THE INOTRICATIONS
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS
	FOR THIS FORM AND THAT THE INFORMATION STATED  ABOVE IS TRUE AND CORRECT.
	<b>.</b>
	$\sim$ 1 $\sim$ 1
Signatur	re: Telephone No.: (563) 599-8440
Oignatui	(Transferor)
1 11	located west side of house
1011	10 Catua West side of "



# TIME OF TRANSFER INSPECTION TOT# 1673 ROBB HARTER CERT # 9343

-Site Information -

Parcel Description: 160320000700

Address: 2145 235th Ave., Manchester, IA 52057

County: Delaware

Owner Information

Property is owned by a business: No

**Business Name:** 

Owner Name: Wall, Dustin W & Hawker, Jennifer W

Email Address:

Address: 2145 235th Ave., Manchester, IA 52057

Phone No:

Site related information-

No Of Bedrooms: 4

Facility Type: Residential

Last Occupied:

Permit issued by County: Yes

All plumbing fixtures enter septic system: Yes

**Property Information Comments:** 

Inspection Date: 08/12/2022

Currently Occupied: Yes

System Installation Date: 10/05/2013

Permit Number: 2116

County contacted for records: Yes

### Primary Treatment -

### Tank 1

Tank Name: Tank 1

Tank Material: Concrete

No. of Compartments: 2

Date Pumped: 8/12/2022

Distance To Well (Ft.): 126
Risers Intact: Yes

Type: Septic Tank

Tank Corrosion Type: None

Pump Tank Chamber: Yes

Meets Setback to Well: Yes

Is Accessible: Yes

Effluent Filter Present: Yes

Tank Size (Gal): 1500

Liquid Level Type: Normal

Licensed Pumper Name: Harter

Well Type: Private

Lid Intact: Yes

Watertight: Yes

Tank/Vault Pumped: Yes

Inlet Baffle Present: Yes

Outlet Baffle Present: Yes

Functioning as Designed: Yes

Tank Comments: Functioning as designed.

**General Primary Treatment Comments:** 

Distribution Type-

**Distribution Box 1** 

Label: Distribution Box 1

Box Opened: Yes Watertight: Yes

Material Type: Plastic

Baffle Present: No

Functioning As Designed: Yes

Accessible: Yes

Speed Levelers Present: No

General Distribution System Comments: 5ft 8in depth

Secondary Treatment

Absorption Bed1

Distribution Type: Distribution Box

Absorption Bed Length: 60

Gallons Loaded: 400

Distance To Well (Ft.): 166

Grass Cover Present: Yes

Functioning as Designed: Yes

Comments:

Material Type: Rock and PVC Pipe

Total Absorption Area: 1200

Meets Setback to Well: Yes

Absorption Bed Probed: Yes

System Located on Owner Property: Yes Easement Present: N/A

Absorption Bed Width: 20

System Hydraulic Loaded: Yes

Well Type: Private

Saturation or Ponding Present: No

**General Secondary Treatment Comments:** 

Narrative Report

TOT Inspection Report Overall Narrative Comments: Everything is in working condition. There is a filter on the lid which needs to be cleaned once a year. Pump tank every 2 to 3 years.



### IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLOS LT. GOVERNOR ADAM GREGG

DIRECTOR KAVLA LYON

## TIME OF TRANSFER INSPECTION TOT# 1673 ROBB HARTER CERT # 9343

Owner Name:

Wall, Dustin W & Hawker, Jennifer W

Address:

2145 235th Ave., Manchester, IA 52057

County:


Delaware


Inspection Date:


08/12/2022


Submitted Date:


8/17/2022














bonzaven reference pla inner wellhead zone: perc lests bnulbjud scceza peuchment egnin bris yswbooff public water supply wells sbuuoq stresms, lokes, hvers (2)eare aldeliuenu elevations Water suction pipe ears Inameosiqar 580 prisante pipe (s) )laya baso lorq Tolbna gnilaixa elecinc MODT ninim ellew yelew lis at: , meyorqmi send ohne agnillewb phone gnib):ud lot dimensions/proj. erty lines atnamazsa sypequas Locate Wap scale: show slope dhon etsalbni nolicenib & Mapping Checkist 1 441, M Flat any construction lasues: Site Evaluation Map page sors' Designer

	42.47859	V160 32 00 0	07 00 Pd
DELAWARE COUNTY BOARD OF SUPERVICERS	-9/34/76 (Print or Type)	Permit No	2116
	23 Jal Aug	Section_32	Township On 1de
OCATION: SEKY S	ck wuly sec 31	7-89-10 Plumbe	Redy Harback
4 cm 2 4 cm	Type Commercial:	Desident	isj: (No. Bedrooms) 7
intures: Stools Lovetories	_ Bath Tuba2 Shower3 Sini Garbago Grinder	Construction Material Co	Sump Pump
ercolation Test: 1	24	Alado by:	the same of the sa
beorption Field: Total length	of leterals <u>17 60 sq. F+</u> Rock	_No of lateral lines ~P:pr Bed	
I certify that the above infor	mation is correct and that all prop	cosed work will be compli	sted in accordance with the
whe Approved	<u>5</u> 週。上	AMPLICAN	TE EIGNATURE
y Derw Ziger	SAL SAL		

1

,