

Document 2022 GWH-2799 Type 53 001 Pages 6 Date 9/19/2022 Time 8:23:02AM Rec Amt \$.00

Daneen Schindler, RECORDER/REGISTRAR DELAWARE COUNTY IOWA

## **REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT**

TO BE COMPLETED BY TRANSFEROR

т	D	Λ	M	c	С	ᆮ	D	o	D	
	n	m	IV	J	г	_	n	v	n	

Name: Kirk M. Conklin and Luann S. Conklin

Address: 1031 140th Ave., Strawberry Point, IA 52076

TRANSFEREE:

Name: Brian G. West and Anne F. West

Address: 211 E Elm Street, Strawberry Point, IA 52076

Address of Property Transferred:

1031 140th Avenue, Strawberry Point, Iowa 52076

Legal Description of Property: (Attach if necessary)

Parcel "B" Being Part Of The Southeast Quarter Of The Northeast Quarter (SE¼-NE¾) Of Section 3, Township 90 North, Range 6 West Of The Fifth Principal Meridian, Delaware County, Iowa, according to plat recorded in Book 2000, Page 578; also Parcel "A" Being Part Of The Southeast Quarter Of The Northeast Quarter (SE½-NE¾) Of Section 3, Township 90 North, Range 6 West Of The Fifth Principal Meridian, Delaware County, Iowa, according to plat recorded in Book 2001, Page 679.

, , , , , , , , , , , , , , , , , , ,
plat recorded in Book 2001, Page 679.
1. Wells (check one)
There are no known wells situated on this property.
☐ There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.
2. Solid Waste Disposal (check one)
There is no known solid waste disposal site on this property.
☐ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.
3. Hazardous Wastes (check one)
There is no known hazardous waste on this property.
☐ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.
4. Underground Storage Tanks (check one)
There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
☐ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.
5. Private Burial Site (check one)
☐ There is a private burial site on this property. The location(s) of the site(s) and known identifying

DNR form 542-0960 (July 18, 2012)

**FILE WITH RECORDER** 

information of the decedent(s) is stated below or on an attached separate sheet, as necessary. 6. Private Sewage Disposal System (check one) ☐ All buildings on this property are served by a public or semi-public sewage disposal system. ☐ This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system. There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording. ☐ There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form. ☐ There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. ☐ There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9] ☐ This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: ☐ The private sewage disposal system has been installed within the past two years pursuant to permit number Information required by statements checked above should be provided here or on separate sheets attached hereto: Wall appares 30' W. of house. Pressure Tank un barement Septic appears 100' what of house I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT. Telephone No.: (563) 580-7857 Signature:



## TOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REVNOLDS LT. GOVERNOR ADAM GREGO

D'RECTOR MAYLA LYON

## TIME OF TRANSFER INSPECTION TOTA 567 DONALD KUEHL

Site Information

Parcel Description: CONKLIN RESIDENCE

Address: 1031 140TH AVE, Strawberry Point, IA 52076 County: Delaware

Owner Information

Property is owned by a business: No

Business Name:

Owner Name: KIRK CONKLIN

Emall Address:

Address: 1031 140TH AVE, Strawberry Point, IA 52076

Phone No:

Site related information

No Of Bedrooms: 3

Facility Type: Residential

Last Occupied:

Permit issued by County: Yes

All plumbing fixtures enter septic system: Yes

Property Information Comments:

Inspection Date: 05/23/2022

Currently Occubied: Yes

System Installation Date: 02/28/2005

Permit Number: 1294

County contacted for records: Yes

Primary Treatment

Tank 1

Tank Name: Tank 1

Tank Material: Concrete

No. of Compartments: 2

Date Pumped: 5/28/2022

Distance To Well (Ft.): 100

Type: Septic Tank

Tank Corrosion Type: None

Pump Tank Chamber: Yes

Meets Setback to Well: Yes

Is Accessible: Yes

Tank Size (Gal): 1250

Liquid Level Type: Normal

Licensed Pumper Name: DONALD

**KUEHL** 

Well Type: Private

Lid Intact: Yes

Risers Intact: Yes Effluent Filter Present: No Watertight: Yes Functioning as Designed: Yes Tank/Vault Pumped: Yes Inlet Baffle Present: Yes Outlet Baffle Present: Yes Tank Comments: General Primary Treatment Comments: Distribution Type **Distribution Box 1** Label: Distribution Box 1 Accessible: Yes Material Type: Plastic Box Opened: Yes Baffle Present: Yes Speed Levelers Present: Yes Watertight: Yes Functioning As Designed: Yes General Distribution System Comments: Secondary Treatment **Lateral Field1** Distribution Type: Distribution Box Material Type: Leaching Chamber Trench Width: 30 Lines: 3 Total Length of Absorption Line: 300 System Hydraulic Loaded: No Gallons Loaded: Meets Setback to Well: Yes Well Type: Private Distance To Well (Ft.): 100 Lateral Lines Probed: Yes Saturation or Ponding Present: No System Located on Owner Property: Yes Grass Cover Present: Yes Lateral Lines Equal Length: Yes Easement Present: N/A Functioning as Designed: Yes Comments: General Secondary Treatment Comments: Narrative Report TOT Inspection Report Overall Narrative Comments: SEPTIC TANK WAS PUMPED AND INSPECTED. NO FILTER WAS IN SYSTEM. D-BOX LEVELS WERE GOOD. SPEED DIALS WERE IN GOOD CONDITION. THE SYSTEM IS IN WORKING CONDITION. THE GRASS HAS BEEN MOWED OVER THE SYSTEM, NO WET SPOTS FOUND.



IOWA DEPARTMENT OF NATURAL RESOURCES

Governor Kim Reynolds Lt. Governor Adam Gregg

Trafettor Rama Ivor

finde of transfer	PINSPECTION TOTA 567 D	ionalo kufhi	- CERT # REL

Owner Name:

KIRK CONKLIN

Address:

1031 140TH AVE , Strawberry Point , IA 5207

County:

Delaware

Inspection Date:

05/23/2022

Submitted Date:

06/02/2022

wellhead zon: ng access cement area ing and/or proposed syste llings and offrer improvem Ilmensions/proj arty lines ping Check ist water supply wells lable area(s) List any construction Issues: Site Evaluation Map (s) indicate north pnge 2 of 2 elevations easements Conklin bortngs phone gas electric pleaf man henchmark show stope desail setbacks all water walls within 100ft bu iding prossure p pe water suction pipe streams, lakes, rivers Hoodway and Idinge % direction smargeid II biagrams

.