

Book 2022 Page 2974

Document 2022 GWH-2974 Type 53 001 Pages 7 Date 10/03/2022 Time 3:18:29PM Rec Amt \$.00

Daneen Schindler, RECORDER/REGISTRAR DELAWARE COUNTY IOWA

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

	_		_	 			
TR	٨	N	c		21	זר	Э.

Name: Michael W. Cole and Lori L. Cole

Address: 16242 188th Street, Manchester, IA 52057

TRANSFEREE:

Name: Jon A. Demmer

Address: 2720 50th Street, Marion, IA 52302

Address of Property Transferred:

16242 188th Street, Manchester, Iowa 52057

Legal Description of Property: (Attach if necessary)

Lot Twenty Two (22) of Prairie Hills Estates, a Subdivision of Parcel C and E in the Southwest Quarter of Section 18, and Parcel C in the Northwest Quarter of Section 19, Township 89 North, Range 5, West of the 5th P.M., according to plat recorded in Book 1999, Page 1731

1. Wells (check one)

- ☐ There are no known wells situated on this property.
- There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

- ☑ There is no known solid waste disposal site on this property.
- ☐ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- ☑ There is no known hazardous waste on this property.
- ☐ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- ☑ There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

- □ There are no known private burial sites on this property.
- ☐ There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

- All buildings on this property are served by a public or semi-public sewage disposal system.
- ☐ This transaction does not involve the transfer of any building which has or is required by law to have a

FILE WITH RECORDER

DNR form 542-0960 (July 18, 2012).

	sewage disposal system.
⊠	There is a building served by private sewage disposal system on this property or a building without any lawfu sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form
	when recording. There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified
	inspection. A copy of the binding acknowledgment is attached to this form. There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
	This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to permit number
Informa heretos	ation required by statements checked above should be provided here or on separate sheets attached:
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
Signatu	1020m
	All Colonial Value



DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 2350 BILL DOWNS **CERT #8880**

-Site Information-

Parcel Description: Mike Cole

Address: 16242 188th St., Manchester, IA 52057

County: Delaware

Owner Information-

Property is owned by a business: No

Business Name:

Owner Name: Mike Cole

Email Address:

Address: 16242 188th St., Manchester, IA 52057

Phone No: 319-551-9955

Additional Contact Information -

Name

Email Address

Affiliate Type

Dwight Hettinger

dwight@exitunlimited.com

Realtor

Site related information -

No Of Bedrooms: 3

Facility Type: Residential

Last Occupied:

Permit issued by County: Yes

All plumbing fixtures enter septic system: Yes

Currently Occupied: Yes System Installation Date: 07/07/2015

Inspection Date: 09/19/2022

Permit Number: 2401

County contacted for records: Yes

Property Information Comments:

Primary Treatment-

Tank 1

Tank Name: Tank 1

No. of Compartments: 2

Tank Material: Concrete

Type: Septic Tank

Tank Corrosion Type: None

Pump Tank Chamber: No

Tank Size (Gal): 1500

Liquid Level Type: Normal

Licensed Pumper Name: BIII Downs

Date Pumped: 9/2/2022

Distance To Well (Ft.): 100

Risers Intact: Yes

Meets Setback to Well: Yes

Effluent Filter Present: Yes

Well Type: Private

Is Accessible: Yes

Lid Intact: **Yes**Watertight: **Yes**

Tank/Vault Pumped: Yes

Inlet Baffle Present: Yes

Outlet Baffle Present: Yes

Functioning as Designed: Yes

Tank Comments:

General Primary Treatment Comments:

Distribution Type

Distribution Box 1

Label: Distribution Box 1

Box Opened: Yes

Material Type: Plastic and Concrete

Baffle Present: No

Accessible: Yes

Speed Levelers Present: Yes

Watertight: Yes

Functioning As Designed: Yes

General Distribution System Comments:

Secondary Treatment

Lateral Field1

Distribution Type: Distribution Box

Lines: 3

Gallons Loaded: 325

Distance To Well (Ft.): 100

Grass Cover Present: Yes

Easement Present: N/A

Comments:

Material Type: Rock and PVC Pipe

Total Length of Absorption Line: 300

Meets Setback to Well: **Yes**Lateral Lines Probed: **Yes**

Lateral Lines Equal Length: Yes

Functioning as Designed: Yes

Trench Width: 24

System Hydraulic Loaded: Yes

Well Type: Private

Saturation or Ponding Present: No

System Located on Owner Property: Yes

General Secondary Treatment Comments:

Narrative Report-

TOT Inspection Report Overall Narrative Comments: System working as it should.



IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLDS LT. GOVERNOR ADAM GREGG

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 2350 BILL DOWNS CERT # 8880

Owner Name:

Mike Cole

Address:

16242 188th St., Manchester, IA 52057

County:

Delaware

Inspection Date:

09/19/2022

Submitted Date:

9/27/2022

