Recorded: 11/28/2022 at 2:11:47.0 PM

County Recording Fee: \$0.00 Iowa E-Filing Fee: \$0.00 Combined Fee: \$0.00

Revenue Tax:

Delaware County, Iowa Daneen Schindler RECORDER

BK: 2022 PG: 3497

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT TO BE COMPLETED BY TRANSFEROR

TRANSF	EROR:					
Name (Charles A. Amsbary					
Address	1906 Rainbow Drive	Waterloo	IA	50701		
	Number and Street or RR	City, Town or PO	State	Zip		
TRANSF	EREE:					
Name k	Kevin R. Schmitt and Valorie A. Schmitt					
Address	12066 Tyra Lane	Dubuque	IA	52003		
	Number and Street or RR	City, Town or PO	State	Zip		
Address	of Property Transferred:					
20661 - 26	64th Street	Delhi	IA	52223		
Number an	d Street or RR	City, Town or PO	State	Zip		
	scription of Property: (Attach if necessary) ned legal description.					
Ŭ Tŀ □ Tŀ	(check one) nere are no known wells situated on this property is a well or wells situated on this property for the property is a set of the property in the property is a set of the property is a s	erty. The type(s), location(s) and	d legal status are st	ated below		
or set forth on an attached separate sheet, as necessary. 2. Solid Waste Disposal (check one) There is no known solid waste disposal site on this property. There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.						
3. Hazardous Wastes (check one) There is no known hazardous waste on this property. There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.						
 4. Underground Storage Tanks (check one) There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.) There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary. 						

5.	P <u>ri</u> vate Burial Site (check one)					
	N There are no known private burial sites on this property					
	There is a private burial site on this property. The location(s) of the site(s) and known identifying information					
	of the decedent(s) is stated below or on an attached separate sheet, as necessary.					
6.	Private Sewage Disposal System (check one)					
	All buildings on this property are served by a public or semi-public sewage disposal system.					
	This transaction does not involve the transfer of any building which has or is required by law to have a					
	sewage disposal system.					
	Thora is a building against the same of th					
_	There is a building served by private sewage disposal system on this property or a building without any					
	idwird sewage disposal system. A certified inspector's report is attached which documents the condition of					
	the private sewage disposal system and whether any modifications are required to conform to standards					
	adopted by the Department of Natural Resources. A certified inspection report must be accompanied by					
	this form when recording.					
	There is a building served by private sewage disposal system on this property. Weather or other temporary					
	physical conditions prevent the certified inspection of the private sewage disposal system from being					
	conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct					
	a certified inspection of the private sewage disposal system at the earliest practicable time and to be					
	responsible for any required modifications to the private sewage disposal system as identified by the					
	certified inspection. A copy of the binding acknowledgment is attached to this form.					
	There is a building served by private sewage disposal system on this property. The buyer has executed a					
	binding acknowledgment with the county board of health to install a new private sewage disposal system					
	on this property within an exceed upon time ported A carried the bird bird by private sewage disposal system					
	on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.					
	There is a building served by private sewage disposal system on this property. The building to which the					
	sewage disposal system is connected will be demolished without being occupied. The buyer has executed					
	a binding acknowledgment with the county board of health to demolish the building within an agreed upon					
	time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]					
	☐ This property is exempt from the private sewage disposal inspection requirements pursuant to the following					
	Exemption [Note: for exemption #9 use prior check box]:					
	☐ The private sewage disposal system has been installed within the past two years pursuant to permit number					
	The past two years pursuant to permit number					
Inf	ormation required by statements checked above should be provided here or on separate sheets					
att	ached hereto:					
,						
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM					
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.					
٥.						
Sig	nature: Telephone No.: (954) 805-9145					
	(Transferor or Agent)					

Lot One Hundred Eleven (111) of "Clair-View Acres at Delhi, Iowa" in Sections 23 and 26, Milo Township, Delaware County, Iowa, according to plat recorded in Book 2, Plats, Page 200; also Parcel T Part Of Lot 117 And Part Of Vine Avenue Of Clair View Acres, Section Twenty-Six, Township Eighty-Eight North (T88N), Range Five West (R5W) Of The Fifth Principal Meridian, Delaware County, Iowa, according to plat recorded in Book 2000, Page 2564.



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information Current Owner 7000 Kelly / Buyer Malling Address 340 0 740 in the	TOTAL STATE OF THE
Current Owner	20.00
Buyer Joo Sell	MCMADUS
Mailing Address 34/2	Realton
Current Owner 1000 (Kelly / Buyer Mailing Address 340 N Junipen Site Address/County 2066 / 20	Cl 19 Epch.
Site Address/County 2066 / 26 No. of Bedrooms Z Last Occupied Smooth!	BORHU Liberty +A 69
one Address/County_2066	11 11 1
N. C.	To Delli
No. of Bedrooms Z Last Occupied? 5 mouth	Comments of Comments of the co
Disp.	osal? Y (N) Softener? Y (N) 11.1 Grand of the
Records Available Vas Permit/Tractallation	ome suppry? Exe
No. of Bedrooms Z Last Occupied? 5 Mouth Disport Records Available 1/25 Permit/Installation Date Septic System Information	$\frac{1993}{1000}$ Installer $\frac{300}{1000}$
Septic System Information	and the same of th
Septic Tank(s): Size	.a
Tank Pumped? Material	SONGREAGE CONDITION STAND
Septic/Trash/Processing Tonly St.	Licensed Pumper
Tank pumped? //// Name: Size	faterial Cartination
Date 4-22-2	2 Licensed Dumen Condition Soci
Septic System Information Septic Tank(s): Size Tank Pumped? Septic/Trash/Processing Tank: Size Tank pumped? Aerobic treatment unit (ATU) MEGR	- AABER
Tank Process to	and the same of th
Maintenant Date	Size
Condition Date Expiration Date	Licensed Pumper
	Service Proviner
Aerobic treatment unit (ATU) MFGR Tank Pumped? Date Maintenance Contract? Expiration Date Condition	A September 1997
tump ranks/Vaults: Type Size	A STATE OF THE PARTY OF THE PAR
Diowika a	Condition
	mili-1. The second
Distribution System: Distribution Box Ver On Header Pipe(s) NO Pressure Docada	Condition OK
Pressure Doged?	Number of Lines
100001 /VC	The of security is a second se
Secondary Treatment	
ength of Absorption Fields 2) (103)	- O
ondition of Fields OE	_ Determined by Pros
condary Treatment Length of Absorption Fields 2 / 100/ Condition of Fields 0 & Type of Trench Material 100/2 3 P.P.C.	Determined by Nondo LCL
	July 1 Comment of the
ize of Sand Filter	
ent Pipes Above Grade?	Determined by
ffluent Sample Taken?	Discharge Pipe Located?
The same of the sa	Results
ledia Filters: Type	- 1) pulprises a few of the second se
re of Sand Filter Yent Pipes Above Grade? Iffluent Sample Taken? Iedia Filters: Type Itaintenance Contract?	
CHILDINICA L'OTTENO ACO	
ondition Expiration Date	Service Provider
ondition Expiration Date	Service Provider
ledia Filters: Type	Service Provider



Time of Transfer Inspection Worksheet

Other Components		
Alarms Working?	Disinfection Wo	ماسئت ۵۰۰
Control Box Timers	wo	
Other Components		Standard Waster
Overall condition of the private sewage disposal sys	A CONTRACTOR DESCRIPTION OF THE PROPERTY OF TH	
Acceptable?	2.44 A	
Explain (attach additional pages as needed):	in working Conten	And the second s
Comments: Keep took pump ever	, 3-4 YeAns	
Site status at conclusion of Time of Transfer inspect	ion:	A Secretary Secretary of Secret
Verify that controls are set on the appropriate mode. Power is on to all components. Revisit all components to verify lids are secure. Gather all tools for removal from the site. Verify that no sewage is on the ground surface.		
Using this worksheet, write a narrative report of the i	nspection results.	
Submit a copy of this report, including your narrative DNR and the county Recorder in the county where the		al bealth office, the
This report indicates the condition of the private sews does not guarantee that it will continue to function sa		f the inspection. It
Signature of Certified Inspector. Name (print): Robb Harter	Date:4-2	22-22
Address: 3031 160th Street Dyersville, Iowa 52040 Phone # 563-542-1010	Date: 4-2 Certficate	#: 68
		10

Beacon[™] Delaware County, IA



Parcel ID

250230712800

Sec/Twp/Rng 23-88-5

Brief Tax Description

Property Address 20661 264TH ST

DFLHI

Class Acreage

Alternate ID n/a

Owner Address McManus, Todd E & Kelly J

340 N Juniper St North Liberty, IA 52317 , well

th o

Corporate Limits Political Township

Legend

BLL Parcel Roads

District

MILO MAQ. V. LAKE FD 12

CLAIR VIEW ACRES

LOT 111 & PARCEL T

PTLOT117

(Note: Not to be used on legal documents)

Disclaimer: All critical information should be independently verified. If you have questions about this site please contact either the Delaware County Auditor's Office at 563 927-4701 or the Delaware County Assessor's Office at 563 927-2526

Date created: 4/28/2022

Last Data Uploaded: 4/28/2022 3:45:22 AM

10 is 8" under Patio Block. D Box is

3 Ft East of thor 12" Deep @ Indi out WHAN BOCK? Pipe. Well over 200Ft EAST of thok Sce Pic