

Book 2023 Page 896

Document 2023 GWH-896 Type 53 001 Pages 15 Date 4/27/2023 Time 9:48:50AM Rec Amt \$.00

Daneen Schindler, RECORDER/REGISTRAR DELAWARE COUNTY IOWA

#### REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

If the transaction is exempt from filing a declaration of value pursuant to Iowa Code 428A.1(2), STOP HERE. Pursuant to Iowa Code section 558.69(1), when no declaration of value is submitted during a transaction, you are not required to submit a groundwater hazard statement or include the statutory language in Iowa Code section 558.69(8A). Please consult your realtor or legal counsel for further advice, including on whether a declaration of value is required. The Department provides this information for statutory reference only.

Instructions for this document can be found at: https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960%20Instructions.pdf

Attachment 1, if required, can be found at: https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960a.pdf

#### TRANSFEROR:

Name: Kurt A. Osterhaus and Christy M. Osterhaus Address: 703 8th Ave SE, Dyersville, IA 52040

#### TRANSFEREE:

Name: Michael J. Kruse and Lois A. Kruse Address: 2925 160th St, Dyersville, IA 52040

Address of Property Transferred: 1601 300th Ave, Dyersville, Iowa 52040

Legal Description of Property: (Attach if necessary)

The North nine (9) rods of the East eighteen (18) rods of the Northeast Quarter (NE¼) of the Northeast Quarter (NE¼) of Section Five (5), Township Eighty Nine (89) North, Range Three (3), West of the Fifth P.M.

## 1. Wells (check one) No Condition - There are no known wells situated on this property. Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary. 2. Solid Waste Disposal (check one) No Condition - There is no known solid waste disposal site on this property. Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Haza	rdous Wastes (check one)
	No Condition - There is no known hazardous waste on this property.
	Condition Present - There is hazardous waste on this property and information related thereto is provided in
	Attachment #1, attached to this document.
4. Unde	erground Storage Tanks (check one)
$\nearrow$	No Condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and
´_ \	residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
Ш	Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.
	substance(s) contained are listed below of on an attached separate sheet, as necessary.
5. Priva	te Burial Site (check one)
$\mathbb{X}$	No Condition - There are no known private burial sites on this property.
⊔ \	Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.
	information of the decedent(s) is stated below of on an attached separate sheet, as necessary.
6. Priva	te Sewage Disposal System (check one)
	No Condition - All buildings on this property are served by a public or semi-public sewage disposal system.
	No Condition - This transaction does not involve the transfer of any building which has or is required by law to have a
VI	sewage disposal system.  Condition Present - There is a building served by private sewage disposal system on this property or a building without
*	any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the
_	private sewage disposal system and whether any modifications are required to conform to standards adopted by the
_	Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
	Condition Present - There is a building served by private sewage disposal system on this property. Weather or other
	temporary physical conditions prevent the certified inspection of the private sewage disposal system from being
	conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required
	modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding
	acknowledgment is attached to this form.
	Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to
	ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding
	acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
	Condition Present - There is a building served by private sewage disposal system on this property. The building to which
	the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding
	acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of
	the binding acknowledgment is provided with this form. [Exemption #7]
	Condition Present - There is a building served by private sewage disposal system on this property. This property is exempt from the private sewage disposal inspection requirements pursuant to the following Exemption [Note: for
	exempt from the private sewage disposal inspection requirements pursuant to the following Exemption [Note: for exemption #7 use prior check box]:
	Condition Present - There is a building served by private sewage disposal system on this property. The private sewage
	disposal system has been installed within the past two years pursuant to permit number:

#### Review the following two directions carefully:

A. If you selected a box stating "No Condition" for <u>every</u> numbered section above, <u>STOP HERE</u>. Do not submit this form. Instead, pursuant to lowa Code section 558.69(8A), you must include the following language on the first page of the recorded deed, instrument, or other writing:

February 15, 2023 FILE WITH RECORDER DNR Form 542-0960

"There is no known private burial site, well, solid waste disposal site, underground storage tank, hazardous waste, or private sewage disposal system on the property as described in Iowa Code section 558.69, and therefore the transaction is exempt from the requirement to submit a groundwater hazard statement."

Please consult your realtor or legal counsel for further advice on this exemption. By law, the owner of the property is responsible for the accuracy of this statement, and the Department provides this information for statutory reference only.

B. If you checked <u>any</u> box stating "Condition Present" for <u>any</u> of the numbered sections above, continue below. You must complete this form, including providing all required information, and you must submit this form to the county recorder's office with declaration of value.

	statements checked above sho	uld be provided here	or on separate sheets at	ttached hereto:
Well locate	ed approx 3	3 SE il	Bldg.	
	от отри		0	
				<del></del>
	•		-	
			<del></del> -	
:		•		
I HEREBY DECLARE THAT	I HAVE REVIEWED THE INSTR	<b>UCTIONS FOR THIS</b>	FORM AND THAT THE	<b>INFORMATION STATED</b>
ABOVE IS TRUE AND <del>COR</del>	RECT			•
Signature:		Telephone No.: (563	) 543-6788	
	Fransferor)			



#### IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLDS LT. GOVERNOR ADAM GREGG

DIRECTOR KAYLA LYON

## TIME OF TRANSFER INSPECTION TOT# 3686 ROBB HARTER

Site Information

Parcel Description: 180050100100

Address: 1601 300th Ave, Dyersville, IA 52040

County: Delaware

Owner Information

Property is owned by a business: No

**Business Name:** 

Owner Name: Kurt A & Christy M Osterhaus

Email Address:

Address: 703 8th Ave SE, Dyersville, IA 52040

Phone No:

Site related information

No Of Bedrooms: 3

Facility Type: Residential

Last Occupied:

Permit issued by County: Yes

All plumbing fixtures enter septic system: Yes

**Property Information Comments:** 

Inspection Date: 12/13/2022

Currently Occupied: Yes

System Installation Date: 09/02/2016

Permit Number: 2542

ounty contacted for records: Yes

**Primary Treatment** 

Tank Name: Tank

Tank Material: Concrete

No. of Compartments: 2

Date Pumped: 12/13/2022

Distance To Well (Ft.): 100+

Risers Intact: Yes

Type: Septic Tank

Tank Corrosion Type: None

Pump Tank Chamber: Yes

Meets Setback to Well: Yes

Is Accessible: Yes

Effluent Filter Present: Yes

Tank Size (Gal): 1500

Liquid Level Type: Normal

Licensed Pumper Name: Harter

Well Type: Private

Lid Intact: Yes

Watertight: Yes

Tank/Vault Pumped: Yes

Inlet Baffle Present: Yes

Outlet Baffle Present: Yes

Functioning as Designed: Yes

Tank Comments:

**General Primary Treatment Comments:** 

Distribution Type

Distribution Box

Label: Distribution Box

Box Opened: Yes

Watertight: Yes

Material Type: Plastic

Baffle Present: Yes

Functioning As Designed: Yes

Accessible: Yes

Speed Levelers Present: Yes

General Distribution System Comments:

Secondary Treatment

Lateral Field

Distribution Type: Distribution Box

Lines: 3

Gallons Loaded: 300

Distance To Well (Ft.): 100+

Grass Cover Present: Yes

Easement Present: N/A

Comments:

Material Type: Rock and PVC Pipe

Total Length of Absorption Line: 300

Meets Setback to Well: Yes

Lateral Lines Probed: Yes

Lateral Lines Equal Length: Yes

Functioning as Designed: Yes

Trench Width: 24

System Hydraulic Loaded: Yes

Well Type: Private

Saturation or Ponding Present: No

System Located on Owner Property: Yes

General Secondary Treatment Comments:

Narrative Report

TOT Inspection Report Overall Narrative Comments: System in good working condition. Pump tank every 3 years.



#### **IOWA DEPARTMENT OF NATURAL RESOURCES**

GOVERNOR KIM REYNOLDS LT. GOVERNOR ADAM GREGG

DIRECTOR KAYLA LYON

# TIME OF TRANSFER INSPECTION TOT# 3686 ROBB HARTER CERT # 9343

Owner Name:

**Kurt A & Christy M Osterhaus** 

Address:

1601 300th Ave , Dyersville , IA 52040

County:

**Delaware** 

Inspection Date:

12/13/2022

Submitted Date:


1/6/2023

This page certifies a Time of Transfer inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).

DELAWARE COUNTY BOARD OF SUPERVISORS	(Print or Type)	Permit No	2542
APPLICATION FOR PERMIT	TOTAL HATTAIN ATT	BEWARE DICEOGRAL AV	
ADDRESS: 1601 38004 A. LOCATION: 180050100 -	Denseille.	Section 5	Township Brame
LOCATION: 18 00 50 100 100 -	5-89-3		
Owner: Mark Kn. Porr Tens	)nt:	Plumber: .	Donert
Lot Size: 1.02 Type Commercial Stools 1 Levatories Bath Tubs	nercial:		(No. Bedrooms). 3
Fixtures: Stools_1 Levatories_ Bath Tubs_	Showers Sinks 2	Automatic Laundry	Sump Pump
Septic Tank made by Swall Garbage Gri	nder Cons	truction Material	Gelions Cap. 1503
Percolation Test: 1	3 4	_ Made by:	
Percolation Test: 1	3 /125 3 210 No	o, of lateral lines	3-701:-
This system is new X Existing	2/	or + Inf./tra	4.
i certify that the above information is correct	t and that all proposed	work will be completed	I in accordance with the
Delevere County Regulations.	<b>~</b> •		•
Dete Approved 9-2-16	John	A Boner	<b>*</b>
or Dann Leva	SEAL	APPLICANT'S	BIGNATURE

#### **DELAWARE COUNTY SANITATION** EnvTrack# Application # Permit # Completion Report for Private Sewage Disposal System Owner: Site Address: Township: Parcel #: Legal S-T-R Mailing Address: Contractor: Bedroom #: Water Supply: Longitude: Primary Treatment: Septic Tank Volume (g): Swale, Manuf: Swale, Material: Crede # Pieces: Riser Ht Lid 2 (in): Filter Brand: Doly Riser Ht Lid 1 (in): Diameter (in): Note: Effluent filter requires frequent cleaning. Dose Tank Volume(g): NP Pump or Siphon Dose: \_\_\_\_ Gallons/dose: \_\_\_ Riser Ht (in): \_\_\_\_ Alarm: \_\_\_ D-Box: Longitude; Lineal Ft: Subsurface Absorption Type: Chamber Manuf: # Trenches: Inches rock under pipe: Trench Depth (in): Trench width (in): Distance to well (ft): Overall width (ft): Surface Absorption Type: Overall length (ft): Rock bed width (ft): Rock bed length (ft): Length of laterals (ft): # Laterals: Header pipe diameter (in): Rock type: Distance to well (ft): Depth to bottom of trench (in): Sand filter width (ft): Sand filter sq ft: #Collector lines: Packed Bed Media Filter: Sand filter length(ft): Distance to well (ft): # Distributor lines: Distributor line type: Separating layer: Discharge GPS (lat x long): \*Peat Filter: Serial #: # Laterals: Closed or Open bottom: Lineal Ft absorption: Trench width (ft): Rock under pipe (in): crushed rock, river rock or chamber Distance to well (ft): Inches soil cover over trench: Discharge GPS (lat x long): \*Recirculating Textile Filter: Brand Name: Absorption field installed after (no discharge) Distance to well (ft): \*Note: A maintenance agreement with a manufacturer-approved contractor must be maintained for the life of the septic system. Comments: Effluent filter requires frequent cleaning. Was any portion of the field covered before the inspection: no System installation approved: Date of Final Inspection: 9-6 Environmental Health Specialist: Scanned -

This APPROVAL in no way makes the County responsible for the continued operation of this sanitation system



# PRIVATE ON-SITE SEWAGE DISPOSAL REPORT ON SOIL BORINGS & PERCOLATION TESTS

2542

#### A. GENERAL INFORMATION

(1) Applicant: John Boner	t / Mark Knipper		Phone: (563) 599-1825 John
(2) Address: 1601 300th Ave	. Dyersville, IA 52040		
(2a) Name of Consulting En	gineer: BUESING & ASSOC	CIATES, INC.	
(3) Location of Property: No	orth 9 Rods of the East 18 Ro	is of the NE1/4 NE1	/4 of Section 05, T89N, R3E
(4) Name of current property	owner: MARK KNIPPER		
(5) Type of Occupancy:	X single family residential multi-family residential mobile home	l	business or commercial industrial recreational
(6) Structure is: X exis	ting _ proposed (	Occupancy will be:	other X permanent temporary
B. SITE INFORMATION			
(7) Lot Net Area: 1.02 Acre	s		
(8) Water Supply: X p	rivate well common wel	l municipal w	ater
(9) Water Supply is: _X_ e	xisting proposed		
(10) Site is: > 100 Ft. from	_X_ existing well, pr	oposed, oradjoi	ning well's
(11) Site is:Upslope	X Downslope from X	existing well,	_ proposed, or adjoining well's
(11a) Existing Slope: 11-159	% Slope Trends: Wi	EST	
(12) Dominant soil type: 16	Name: DOW	NS	
(13) Dominant textural descri	ription of soil: SILT LOAM		
C. DESIGN INFORMATIO	ON:		1
(14) Fixtures: stools/uris laundry fi floor drai	acility YES garbage grind	o tub/show er NO water sof NO other:	er I shower 0 tener YES sinks 2
(15) No. of bedrooms: 3.	No. of Occupants: 1	Total No. of roo	ms: 6
(16) Fixtures in basement?	NO Type of basement:	walkout _X_l	puried no basement
(17) No. of housing units co	nnected: 1 Facility will be	used: X continua	ally _intermittently

_		
DECKEN	INTOD	MATION:

- (18) Design flow rate (Q): 450 gpd.
- (19) Waste water application rate: 0.8 gal/sq ft/day
- (20) Proposed septic tank size: 1500 gallons.
- (21) Proposed type of system and size (Be specific) PROPOSED 1500 GALLON SEPTIC TANK, DISTRIBUTION BOX AND

  ABSORPTION FIELD -- 5 LINES @ 9' O.C. (3' TRENCH WIDTH) @ 38' LONG (2' DEEP) WITH 12" OF GRAVEL

  BEDDING, CONTRACTOR SEE NOTES ON DRAWING.

PLAN VIEW & SYSTEM LAYOUT - Locate positions of percolation tests and soil borings. Locate all structures, driveways, parking areas, fence line, proposed or existing well and proposed or existing easements. Please locate septic tank, distribution box, lateral field, influent lines, manholes, etc. on plan view.

#### SEE ATTACHED DRAWING

NOTE: Please draw to an appropriate scale

I hereby certify that this engineering document was prepared by me or under my direct personal supervision and that I am a duly licensed Professional Engineer under the laws of the State of Iowa.

SEAL

(signature) Kenneth L. Buesing

My license renewal date is December 31, 2016.

Pages or sheets covered by this seal:

### **SOIL BORING TEST**

#### DATE TESTED: 8-23-16

**TESTED BY: JCH** 

Test No.	Total Depth	Depth to Gr	ound Water	Depth to	Bedrock	Character of Each Soil Layer			
		Observed	Estimated	Observed	Estimated	with Thickness in Inches			
S8-1	60*	47*			>60°	0-20" TOPSOIL 20-25" DARK BROWN SILT LOAM 25-32" BROWN, ORANGE & GRAY SILTY CLAY LOAM 32-36" BROWN, ORANGE & GRAY SILTY CLAY LOAM & RUSTY CLAY 38-50" GRAY CLAY WITH ORANGE & RUSTY CLAY 50-60" GRAY CLAY WITH ORANGE & RUSTY CLAY (VERY WET) HAD 47" TO TOP OF WATER			
SB-2	60"		>60*		>60"	0-15" TOPSOIL 15-34" BROWN SILT LOAM 34-56" BROWN, ORANGE & GRAY SILTY CLAY LOAM 56-60" BROWN, ORANGE & GRAY SILTY CLAY LOAM WITH RUSTY CLAY (WET)			
	<u> </u>					<u></u>			


PERCOLATION TEST LOG DATE TESTED: 8-24-16

**TESTED BY: JCH** 

PRODEITION IDECTOR				27172 120120: 0-24-10				120120 21.7011			
Test No.	Total Depth	Soaking Period	Swell Period	Water in hole after wetting	Test Interval	Test Duration	Drop in Water level (inches)			Rate	
	(inches)	(hrs)	(hrs)	(Inches)	(min)	(hrs)	2nd to last period	next to last period	last period	(min/in)	
P-1	24"	24	24	0"	30	2.0	7.00	6.625	6.00	4.59	
P-2	24"	24	24	0"	30	2.0	6.75	5.75	5.875	4.90	
P-3	24"	24	24	0"	30	2.0	7.50	7.375	7.25	4.07	
		_									

AVERAGE RATE 4.52 min/in

DESIGN RATE: 6-10 min/in



# Beacon™ Delaware County, IA



Parcel ID Sec/Twp/Rng 180050100100

5-89-3

Property Address 1601 300TH AVE

**DYERSVILLE** 

District

BREMEN

**Brief Tax Description** 

N9X18RDSNENE

(Note: Not to be used on legal documents)

Owner Address Knipper, Mark A & Carmen M 3332 Windmill Rd

Hopkinton, IA 52237

2015 Orthophotography Disclaimer. The information in this web site represents current data from a working file which is updated continuously. Information is believed reliable, but its accuracy cannot be guaranteed. No warranty, express or implied, is provided for the data herin, or its use. Special assessments not shown.

Alternate ID n/a

Acreage n/a

Class

Date created: 9/6/2016 Last Data Uploaded: 9/6/2016 1:01:57 AM



Developed by The Schneider Corporation

# Beacon<sup>™</sup> Delaware County, IA



Parcel ID Sec/Twp/Rng 180050100100

5-89-3

Property Address 1601 300TH AVE

**DYERSVILLE** 

District

**Brief Tax Description** 

BREMEN

N 9X 18 RDS NE NE

(Note: Not to be used on legal documents)

Class

Acreage

Owner Address Knipper, Mark A & Carmen M 3332 Windmill Rd

Hapkinton, IA 52237

2015 Orthophotography Disclaimer. The information in this web site represents current data from a working file which is updated continuously. Information is believed reliable, but its accuracy connot be guaranteed. No warranty, express or implied, is provided for the data harin, or its use. Special assessments not shown.

R

n/a

Date created: 8/29/2016 Last Data Uploaded: 8/29/2016 1:01:58 AM



Developed by . The Schneider Corporation