

BK: 2024 PG: 2054

Recorded: 8/23/2024 at 9:26:43.0 AM

Pages 9

County Recording Fee:

Iowa E-Filing Fee: \$0.00

Combined Fee:

Revenue Tax: \$0.00

BRANDY L. MACUMBER, RECORDER

Madison County, Iowa

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT
TO BE COMPLETED IN FULL BY TRANSFEROR

If the transaction is exempt from filing a declaration of value pursuant to Iowa Code 428A.1(2), **STOP HERE**. Pursuant to Iowa Code section 558.69(1), when no declaration of value is submitted during a transaction, you are not required to submit a groundwater hazard statement or include the statutory language in Iowa Code section 558.69(8A). Please consult your realtor or legal counsel for further advice, including on whether a declaration of value is required. The Department provides this information for statutory reference only.

Instructions for this document can be found at:

<https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960%20Instructions.pdf>

Attachment 1, if required, can be found at: <https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960a.pdf>

TRANSFEROR:

Name Jane E. Jensen

Address 3381 140th Street, Cumming, IA 50061

Number and Street or RR

City, Town or PO

State

Zip

TRANSFeree:

Name Zachary Wray and Jennifer Wray

Address 3381 140th Street, Cumming, IA 50061

Number and Street or RR

City, Town or PO

State

Zip

Address of Property Transferred:

3381 140th Street, Cumming, IA 50061

Number and Street or RR

City, Town or PO

State

Zip

Legal Description of Property: (Attach if necessary)

see attached

1. Wells (check one)

- ☒ No Condition - There are no known wells situated on this property.
☐ Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

- ☒ No Condition - There is no known solid waste disposal site on this property.
☒ Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- ☒ No Condition - There is no known hazardous waste on this property.
- ☐ Condition Present - There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- ☒ No Condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

- ☒ No Condition - There are no known private burial sites on this property.
- ☐ Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

- ☒ No Condition - All buildings on this property are served by a public or semi-public sewage disposal system.
- ☐ No Condition - This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
- JJ ☒ Condition Present - There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #7]
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. This property is exempt from the private sewage disposal inspection requirements pursuant to the following Exemption [Note: for exemption #7 use prior check box]: _____
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The private sewage disposal system has been installed within the past two years pursuant to permit number: _____

Review the following two directions carefully:

- A. If you selected a box stating "No Condition" for every numbered section above, **STOP HERE**. Do not submit this form. Instead, pursuant to Iowa Code section 558.69(8A), you must include the following language on the first page of the recorded deed, instrument, or other writing:

"There is no known private burial site, well, solid waste disposal site, underground storage tank, hazardous waste, or private sewage disposal system on the property as described in Iowa Code section 558.69, and therefore the transaction is exempt from the requirement to submit a groundwater hazard statement."

Please consult your realtor or legal counsel for further advice on this exemption. By law, the owner of the property is responsible for the accuracy of this statement, and the Department provides this information for statutory reference only.

- B. If you checked any box stating "Condition Present" for any of the numbered sections above, **continue below**. You must complete this form, including providing all required information, and you must submit this form to the county recorder's office with declaration of value.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

--

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature:

Jane Jensen
(Transferor or Agent)

dotloop verified
08/06/24 6:24 PM CDT
BLKG-1OLP-VOLD-C47P

Telephone No.:

515-681-0251



IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLDS
LT. GOVERNOR ADAM GREGG

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 10988 MIKE HARKIN CERT # 9450**Site Information**Parcel Description: **071012488130000**Address: **3381 140th st, Cumming, IA 50061**County: **Madison****Owner Information**Property is owned by a business: **No**

Business Name:

Owner Name: **Matt & Jane Jensen**

Email Address:

Address: **3381 140th st, Cumming, IA 50061**Phone No: **515-681-0251****Additional Contact Information**

Name

Email Address

Affiliate Type

Matt & Jane Jensen**mjjensen825@yahoo.com****Owner****Brandon Stone****brandonlstone@gmail.com****Realtor****Site related information**No Of Bedrooms: **4**Inspection Date: **07/08/2024**Facility Type: **Residential**Currently Occupied: **No**Last Occupied: **05/01/2024**

System Installation Date:

Permit issued by County: **N/A**

Permit Number:

All plumbing fixtures enter septic system: **Yes**County contacted for records: **Yes**

Property Information Comments:

All waste water appears to go into the septic system**Primary Treatment****Tank 1**Tank Name: **Tank 1**Type: **Septic Tank**Tank Size (Gal): **1250**Tank Material: **Concrete**Tank Corrosion Type: **Moderate**Liquid Level Type: **Normal**

No. of Compartments: 2	Pump Tank Chamber: Yes	Licensed Pumper Name: Wiegert
Date Pumped: 7/8/2024	Meets Setback to Well: N/A	Well Type:
Distance To Well (Ft.):	Is Accessible: Yes	Lid Intact: No
Risers Intact: Yes	Effluent Filter Present: Yes	Watertight: Yes
Tank/Vault Pumped: Yes	Inlet Baffle Present: Yes	Outlet Baffle Present: Yes
		Functioning as Designed: Yes
Tank Comments: 1 chamber lid broken 2 chamber lid gone Pump chamber lid is cracked,high limit alarm is not working		

General Primary Treatment Comments:

There was grease in septic tank,was pumped out, appears to be in working condition,lids need replaced,high limit alarm is not working

Distribution Type

Distribution Box 1

Label: Distribution Box 1	Material Type: Plastic	Accessible: Yes
Box Opened: Yes	Baffle Present: Yes	Speed Levelers Present: Yes
Watertight: No	Functioning As Designed: No	

General Distribution System Comments : **Distribution box is cracked at the bottom,all took water**

Secondary Treatment

Lateral Field1

Distribution Type: Distribution Box	Material Type: Rock and PVC Pipe	Trench Width: 24
Lines: 5	Total Length of Absorption Line: 400	System Hydraulic Loaded: Yes
Gallons Loaded: 300	Meets Setback to Well: N/A	Well Type:
Distance To Well (Ft.):	Lateral Lines Probed: Yes	Saturation or Ponding Present: No
Grass Cover Present: Yes	Lateral Lines Equal Length: Yes	System Located on Owner Property: Yes
Easement Present: N/A	Functioning as Designed: Yes	
Comments: Lateral all took water at time of inspection,there was no ponding on top of laterals		

General Secondary Treatment Comments: **D-box is cracked,all laterals took water at time of inspection**

Narrative Report

TOT Inspection Report Overall Narrative Comments: **All 3 septic lids are broken**

D- box is cracked at the bottom

High limit alarm is not working,

Tank is in fair condition, laterals were

Taking water at time of inspection,no ponding on top of laterals,this is not a guarantee for future operation



IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLDS

LT. GOVERNOR ADAM GREGG

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 10988 MIKE HARKIN CERT # 9450

Owner Name: Matt & jane Jensen

Address: 3381 140th st , Cumming , IA 50061


County: Madison

Inspection Date: 07/08/2024

Submitted Date: 7/9/2024

This page certifies a Time of Transfer inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).

As-built Diagrams



Documents

