



Document 2025 GW1891

Book 2025 Page 1891 Type 43 001 Pages 10

Date 7/23/2025 Time 11:24:41AM

Rec Amt \$.00

INDX

ANNO

SCAN

BRANDY MACUMBER, COUNTY RECORDER
MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT
TO BE COMPLETED IN FULL BY TRANSFEROR

If the transaction is exempt from filing a declaration of value pursuant to Iowa Code 428A.1(2), **STOP HERE**. Pursuant to Iowa Code section 558.69(1), when no declaration of value is submitted during a transaction, you are not required to submit a groundwater hazard statement or include the statutory language in Iowa Code section 558.69(8A). Please consult your realtor or legal counsel for further advice, including on whether a declaration of value is required. The Department provides this information for statutory reference only.

Instructions for this document can be found at:

<https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960%20Instructions.pdf>

Attachment 1, if required, can be found at: <https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960a.pdf>

TRANSFEROR:

Name Stacie Lynn Carter and Chad Carter

Address 1651 S Keystone Street, West Des Moines, IA 50256

Number and Street or RR

City, Town or PO

State

Zip

TRANSFeree:

Name NAF CASH LLC

Address 41050 W 11 Mile Road, Suite 220, Novi, MI 48375

Number and Street or RR

City, Town or PO

State

Zip

Address of Property Transferred:

2325 Carver Road, Winterset, IA 50273

Number and Street or RR

City, Town or PO

State

Zip

Legal Description of Property: (Attach if necessary)

See attached

1. Wells (check one)



No Condition - There are no known wells situated on this property.



Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)



No Condition - There is no known solid waste disposal site on this property.



Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- ☒ No Condition - There is no known hazardous waste on this property.
- ☐ Condition Present - There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- ☒ No Condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

- ☒ No Condition - There are no known private burial sites on this property.
- ☐ Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

- ☐ No Condition - All buildings on this property are served by a public or semi-public sewage disposal system.
- ☐ No Condition - This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
- ☒ Condition Present - There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #7]
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. This property is exempt from the private sewage disposal inspection requirements pursuant to the following
Exemption [Note: for exemption #7 use prior check box]: _____
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The private sewage disposal system has been installed within the past two years pursuant to permit number:

Review the following two directions carefully:

- A. If you selected a box stating "No Condition" for every numbered section above, **STOP HERE**. Do not submit this form. Instead, pursuant to Iowa Code section 558.69(8A), you must include the following language on the first page of the recorded deed, instrument, or other writing:

"There is no known private burial site, well, solid waste disposal site, underground storage tank, hazardous waste, or private sewage disposal system on the property as described in Iowa Code section 558.69, and therefore the transaction is exempt from the requirement to submit a groundwater hazard statement."

Please consult your realtor or legal counsel for further advice on this exemption. By law, the owner of the property is responsible for the accuracy of this statement, and the Department provides this information for statutory reference only.


- B. If you checked any box stating "Condition Present" for any of the numbered sections above, continue below. You must complete this form, including providing all required information, and you must submit this form to the county recorder's office with declaration of value.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

one well	Location -	Section 12
concrete		township 75
Long - 94.024407		Range 28
Lat - 41.313107		
well # 2223239		

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature:


(Transferor or Agent)

Telephone No.: 515-802-6277

Legal attachment

Parcel "A" located in the Northeast Quarter ($\frac{1}{4}$) of the Northwest Quarter ($\frac{1}{4}$) of Section Twelve (12), Township Seventy-five (75) North, Range Twenty-eight (28) West of the 5th Principal Meridian, Madison County, Iowa, containing 3.000 acres, as shown in Plat of Survey filed in Book 2, Page 437 on January 21, 1994, in the Office of the Recorder of Madison County, Iowa.

Locally known as 2325 Carver Road, Winterset, IA 50273



IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLDS
LT. GOVERNOR CHRIS COURNOYER

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 16107 SETH BROWN CERT # 13190

Site Information

Parcel Description: **5601124200100**

Address: **2325 Carver Rd, Winterset, IA 50273**

County: **Madison**

Owner Information

Property is owned by a business: **No**

Business Name:

Owner Name: **Chad & Stacie Carter**

Email Address: **chad.carter@stalkergm.com**

Address: **2325 Carver Rd, Winterset, IA 50273**

Phone No: **515-802-6277**

Additional Contact Information

Name	Email Address	Affiliate Type
Kyle Kuhns	kyle@centralsmhomes.com	Realtor

Site related information

No Of Bedrooms: **3**

Facility Type: **Residential**

Last Occupied:

Permit issued by County: **Yes**

All plumbing fixtures enter septic system: **Yes**

Property Information Comments:

Inspection Date: **06/24/2025**

Currently Occupied: **No**

System Installation Date: **06/10/2015**

Permit Number: **029-15**

County contacted for records: **Yes**

Primary Treatment

Tank 1

Tank Name: **Tank 1**

Tank Material: **Concrete**

No. of Compartments: **3**

Type: **Septic Tank**

Tank Corrosion Type: **Slight**

Pump Tank Chamber: **No**

Tank Size (Gal): **1500/500**

Liquid Level Type: **Normal**

Licensed Pumper Name: **Rogers Septic**

Date Pumped: 6/24/2025	Meets Setback to Well: N/A	Well Type:
Distance To Well (Ft):	Is Accessible: Yes	Lid Intact: Yes
Risers Intact: Yes	Effluent Filter Present: Yes	Watertight: Yes
Tank/Vault Pumped: Yes	Inlet Baffle Present: Yes	Outlet Baffle Present: Yes
		Functioning as Designed: Yes
Tank Comments:		

General Primary Treatment Comments:

Distribution Type

Pump System 1

Label: Pump System 1	Accessible: Yes	Control Box Functioning: Yes
Alarm(s) Present and Functioning: Yes	Functioning As Designed: Yes	

Distribution Box 1

Label: Distribution Box 1	Material Type: Plastic	Accessible: Yes
Box Opened: Yes	Baffle Present: Yes	Speed Levelers Present: Yes
Watertight: Yes	Functioning As Designed: Yes	

General Distribution System Comments :

Secondary Treatment

Lateral Field1

Distribution Type: Distribution Box	Material Type: Leaching Chamber	Trench Width: 36
Lines: 4	Total Length of Absorption Line: 368	System Hydraulic Loaded: Yes
Gallons Loaded: 300	Meets Setback to Well: N/A	Well Type:
Distance To Well (Ft.):	Lateral Lines Probed: Yes	Saturation or Ponding Present: No
Grass Cover Present: Yes	Lateral Lines Equal Length: Yes	System Located on Owner Property: Yes
Easement Present: N/A	Functioning as Designed: Yes	
Comments:		

General Secondary Treatment Comments:

Narrative Report

TOT Inspection Report Overall Narrative Comments: **County map appears to be different from what is there. See attached drawing.**

All wastewater goes to septic. 1500/500 gallon watertight concrete septic/pump tank in working condition with slight deterioration. Accessible by inlet and outlet risers and lids to ground surface. Riser and lid to ground surface over pump

tank. Inlet and outlet baffles present, outlet effluent filter present. 3 compartment tank. Pump and float present and in working condition. Alarm panel(located at tank) and float present and in working condition both visually and audibly. Pumps up to distribution box. Plastic watertight distribution box in working condition. Baffle and speed levelers present. Hydraulic load tested(via pump) 4x92 equaling 368 ft of 36" chambers with 300 gallons. Each lateral took water and probed dry and clean.

TIME OF TRANSFER INSPECTION TOT# 16107 SETH BROWN CERT # 13190

Owner Name: **Chad & Stacie Carter**

Address: **2325 Carver Rd , Winterset , IA 50273**

County: **Madison**

Inspection Date: **06/24/2025**

Submitted Date: **6/24/2025**



Permit # 029-15
Inspection 6/10/15
2325 Carver Rd

