



Document 2025 GW1964

Book 2025 Page 1964 Type 43 001 Pages 8

Date 7/29/2025 Time 2:26:29PM

Rec Amt \$.00

INDX
ANNO
SCANBRANDY MACUMBER, COUNTY RECORDER
MADISON COUNTY IOWA

CHEK

**REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT
TO BE COMPLETED BY TRANSFEROR**

If the transaction is exempt from filing a declaration of value pursuant to Iowa Code 428A.1(2), STOP HERE. Pursuant to Iowa Code section 558.69(1), when no declaration of value is submitted during a transaction, you are not required to submit a groundwater hazard statement or include the statutory language in Iowa Code section 558.69(8A). Please consult your realtor or legal counsel for further advice, including on whether a declaration of value is required. The Department provides this information for statutory reference only.

Instructions for this document can be found at:

<https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960%20Instructions.pdf>Attachment 1, if required, can be found at: <https://www.iowadnr.gov/Portals/idnr/uploads/forms/5420960a.pdf>**TRANSFEROR:**Name Demry Kenneth Hill

Address <u>2981 214th Trl</u>	<u>Winterset</u>	<u>IA</u>	<u>50273</u>
Number and Street or RR	City, Town or P.O.	State	Zip

TRANSFeree:Name Kendra Simmons

Address <u>2981 - 214th Trl</u>	<u>Winterset</u>	<u>IA</u>	<u>50273</u>
Number and Street or RR	City, Town or P.O.	State	Zip

Address of Property Transferred:

<u>2981 214th Trl</u>	<u>Winterset</u>	<u>IA</u>	<u>50273</u>
Number and Street or RR	City, Town or P.O.	State	Zip

Legal Description of Property: (Attach if necessary)

Parcel "E" located in the Northwest Quarter (¼) of the Southwest Quarter (¼) of Section Thirty-three (33), Township Seventy-six (76) North, Range Twenty-six (26) West of the 5th P.M., Madison County, Iowa, containing 3.70 acres, as shown in Plat of Survey filed in Book 2018, Page 3147 on September 28, 2018, in the Office of the Recorder of Madison County, Iowa.

1. Wells (check one)☐ No Condition - There are no known wells situated on this property.☒ Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.**2. Solid Waste Disposal (check one)**☒ No Condition - There is no known solid waste disposal site on this property.☒ Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.Septic

February 15, 2023

FILE WITH RECORDER

DNR form 542-0960

3. Hazardous Wastes (check one)

- ☒ No condition - There is no known hazardous waste on this property.
- ☐ Condition Present - There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- ☒ No condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

- ☒ No condition - There are no known private burial sites on this property.
- ☐ Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

- ☐ No condition - All buildings on this property are served by a public or semi-public sewage disposal system.
- ☐ No condition - This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
- ☒ Condition Present - There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #7]
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. This property is exempt from the private sewage disposal inspection requirements pursuant to the following Exemption [Note: for exemption #7 use prior check box]: _____
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The private sewage disposal system has been installed within the past two years pursuant to permit number: _____

Review the following two directions carefully:

A. If you selected a box stating "No Condition" for **every** numbered section above, **STOP HERE**. Do not submit this form. Instead, pursuant to Iowa Code section 558.69(8A), you must include the following language on the first page of the recorded deed, instrument, or other writing:

"There is no known private burial site, well, solid waste disposal site, underground storage tank, hazardous waste, or private sewage disposal system on the property as described in Iowa Code section 558.69, and therefore the transaction is exempt from the requirement to submit a groundwater hazard statement."


Please consult your realtor or legal counsel for further advice on this exemption. By law, the owner of the property is responsible for the accuracy of this statement, and the Department provides this information for statutory reference only.

B. If you checked **any** box stating "Condition Present" for **any** of the numbered sections above, continue below. You must complete this form, including providing all required information, and you must submit this form to the county recorder's office with declaration of value.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

- Septic System time of transfer done
- Old, non-used well in southwest corner of property

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature:  Telephone No.: 641-208-0369
(Transferor or Agent)



IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLDS
LT. GOVERNOR CHRIS COURNOYER

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 16279 AJ KILLEN CERT # 12978

Site Information

Parcel Description: **Home 2 bed**

Address: **2981 214th Trail Winterset, IA 50273 United St, Winterset, IA 50273** County: **Madison**

Owner Information

Property is owned by a business: **No**

Business Name:

Owner Name: **Demry Hill**

Email Address: **demry.hill@alumni.uni.edu**

Address: **2981 214th Trail Winterset, IA 50273 United St, Winterset, IA 50273**

Phone No: **641-208-0369**

Site related information

No Of Bedrooms: **2**

Facility Type: **Residential**

Last Occupied:

Permit issued by County: **N/A**

All plumbing fixtures enter septic system: **Yes**

Property Information Comments:

Inspection Date: **07/03/2025**

Currently Occupied: **Yes**

System Installation Date:

Permit Number:

County contacted for records: **Yes**

Primary Treatment

Tank 1

Tank Name: **Tank 1**

Tank Material: **Concrete**

No. of Compartments: **1**

Date Pumped: **7/3/2025**

Distance To Well (Ft.):

Type: **Septic Tank**

Tank Corrosion Type: **Moderate**

Pump Tank Chamber: **No**

Meets Setback to Well: **N/A**

Is Accessible: **Yes**

Tank Size (Gal): **750**

Liquid Level Type: **Normal**

Licensed Pumper Name: **Mike killen**

Well Type:

Lid Intact: **Yes**

Risers Intact: **Yes**

Effluent Filter Present: **Yes**

Watertight: **Yes**

Tank/Vault Pumped: **Yes**

Inlet Baffle Present: **Yes**

Outlet Baffle Present: **Yes**

Functioning as Designed: **Yes**

Tank Comments:

General Primary Treatment Comments:

Distribution Type

Distribution Box 1

Label: **Distribution Box 1**

Material Type: **Plastic**

Accessible: **Yes**

Box Opened: **Yes**

Baffle Present: **Yes**

Speed Levelers Present: **Yes**

Watertight: **Yes**

Functioning As Designed: **Yes**

General Distribution System Comments :

Secondary Treatment

Lateral Field1

Distribution Type: **Distribution Box**

Material Type: **Leaching Chamber**

Trench Width: **36**

Lines: **2**

Total Length of Absorption Line: **150**

System Hydraulic Loaded: **Yes**

Gallons Loaded: **150**

Meets Setback to Well: **N/A**

Well Type:

Distance To Well (Ft.):

Lateral Lines Probed: **Yes**

Saturation or Ponding Present: **No**

Grass Cover Present: **Yes**

Lateral Lines Equal Length: **Yes**

System Located on Owner Property: **Yes**

Easement Present: **N/A**

Functioning as Designed: **Yes**

Comments:

General Secondary Treatment Comments:

Narrative Report

TOT Inspection Report Overall Narrative Comments: **Tank is a 750 gallon concrete tank. Single comp with riser and filter. The patio is the top of the tank with plywood in between as form the sides and bottom appear to be in pretty good shape Unknown if it has tar in between plywood and patio. But it did pass inspection in 2018 with the same tank. The box is a plastic 9 hole in good shape went into 2 75 ft laterals that took hydro load even and good system appeared to be in normal working order at time of inspection.**

TIME OF TRANSFER INSPECTION TOT# 16279 AJ KILLEN CERT # 12978

Owner Name: **Demry Hill**

Address: **2981 214th Trail Winterset, IA 50273 United St , Winterset , IA 50273**

County: **Madison**

Inspection Date: **07/03/2025**

Submitted Date: **7/3/2025**

