BK: 2025 PG: 3279

Recorded: 12/3/2025 at 9:14:14.0 AM

Pages 9

County Recording Fee: \$0.00 lowa E-Filing Fee: \$0.00 Combined Fee: \$0.00 Revenue Tax: \$0.00

BRANDY L. MACUMBER, RECORDER

Madison County, Iowa

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED IN FULL BY TRANSFEROR

If the transaction is exempt from filing a declaration of value pursuant to lowa Code 428A.1(2), **STOP HERE**. Pursuant to lowa Code section 558.69(1), when no declaration of value is submitted during a transaction, you are not required to submit a groundwater hazard statement or include the statutory language in lowa Code section 558.69(8A). Please consult your realtor or legal counsel for further advice, including on whether a declaration of value is required. The Department provides this information for statutory reference only.

Instructions for this document can be found at: https://www.iowadnr.gov/media/5465.

Attachment 1, if required, can be found at: https://www.iowadnr.gov/media/5466.

TRANSFEROR:

Number and Street or RR

Name	Bill J. Venhaus a/k/a William J. Venhaus			
Address	2626 160th Street	Van Meter	IA	50261
	Number and Street or RR	City, Town o	r PO Stat	e Zip
TRANSFE	REE:			
Name	Christina Rodriguez			
Address	2626 160th Street	Van Meter	IA	50261
	Number and Street or RR	City, Town or PO	State	Zip
Idress of Pro	perty Transferred:			
2626 160th	Street	Van Meter	lowa	50261

City, Town or PO

State

Zip

Legal Description of Property: (Attach if necessary)

Lot One (1) of Shamrock Hills Subdivision, a Subdivision located in the Northwest Quarter (1/4) of the Northwest Quarter (1/4) of Section Two (2), Township Seventy-six (76) North, Range Twenty-seven (27) West of the 5th P.M., Madison County, Iowa.

AND

Parcel "I" located in Lot Two (2) of Shamrock Hills Subdivision, a Subdivision located in the Northwest Quarter (1/4) of the Northwest Quarter (1/4) of Section Two (2), Township Seventy-six (76) North, Range Twenty-seven (27) West of the 5th P.M., Madison County, Iowa, containing 2.000 acres, as shown in Amended Plat of Survey filed in Book 2012, Page 2185, on July 26, 2012 in the Office of the Recorder of Madison County, Iowa.

	s (check one)
≱	No Condition - There are no known wells situated on this property. Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated
	below or set forth on an attached separate sheet, as necessary.
2. Solid	Waste Disposal (check one)
Þ	No Condition - There is no known solid waste disposal site on this property.
	Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.
	rdous Wastes (check one)
Þ	No Condition - There is no known hazardous waste on this property.
	Condition Present - There is hazardous waste on this property and information related thereto is provided in Attachmen #1, attached to this document.
1. Unde	erground Storage Tanks (check one)
Ø	No Condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
	Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.
5. Priva	ite Burial Site (check one)
Ø	No Condition - There are no known private burial sites on this property.
	Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.
5. Priva	te Sewage Disposal System (check one)
	No Condition - All buildings on this property are served by a public or semi-public sewage disposal system.
	No Condition - This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
Þ	Condition Present - There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
	Condition Present - There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
	Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
	Condition Present - There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #7]
	Condition Present - There is a building served by private sewage disposal system on this property. This property is exempt from the private sewage disposal inspection requirements pursuant to the following Exemption [Note: for

		exemption #7 use prior check box]:
		Condition Present - There is a building served by private sewage disposal system on this property. The private sewage disposal system has been installed within the past two years pursuant to permit number:
	Rev	riew the following two directions carefully:
Α.	Inst	ou selected a box stating "No Condition" for <u>every</u> numbered section above, <u>STOP HERE</u> . Do not submit this form. ead, pursuant to lowa Code section 558.69(8A), you must include the following language on the first page of the orded deed, instrument, or other writing:
		"There is no known private burial site, well, solid waste disposal site, underground storage tank, hazardous waste, or private sewage disposal system on the property as described in lowa Code section 558.69, and therefore the transaction is exempt from the requirement to submit a groundwater hazard statement."
		ase consult your realtor or legal counsel for further advice on this exemption. By law, the owner of the property is consible for the accuracy of this statement, and the Department provides this information for statutory reference only.
В.	con	ou checked <u>any</u> box stating "Condition Present" for <u>any</u> of the numbered sections above, continue below. You must applete this form, including providing all required information, and you must submit this form to the county recorder's see with declaration of value.
Inf	orma	tion required by statements checked above should be provided here or on separate sheets attached hereto:
AΒ		e: Utan Form And That The Information Stated Telephone No.:

GROUNDWATER HAZARD STATEMENT

ATTACHMENT #1

NOTICE OF WASTE DISPOSAL SITE

a. Solid Waste Disposal (check one)
There is a solid waste disposal site on this property, but no notice has been received from the Department of Natural Resources that the
site is deemed to be potentially hazardous.
☐ There is a solid waste disposal site on this property which has been deemed to be potentially hazardous by the Department of Natural
Resources. The location(s) of the site(s) is stated below or on an attached separate sheet, as necessary.
b. Hazardous Wastes (check one)
☐ There is hazardous waste on this property and it's being managed in accordance with Department of Natural Resources rules.
There is hazardous waste on this property and the appropriate response or remediation actions, or the need therefore, have not yet been
determined.
Further descriptive information:
V
I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
Signature: Telephone No.:



GOVERNOR KIM REYNOLDS LT. GOVERNOR CHRIS COURNOYER

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 18499 SETH BROWN CERT # 13190

Site Information

Parcel Description: 400070244014500

Address: 2626 160th St, Van Meter, IA 50261

County: Madison

Owner Information

Property is owned by a business: No

Business Name:

Owner Name: Crystal Venhaus

Email Address: getcarered@yahoo.com

Address: 2626 160th St, Van Meter, IA 50261

Phone No: 515-689-0041

Additional Contact Information

Name

Email Address

Affiliate Type

Sarah Cowman

cowman.sm@gmail.com

Realtor

Site related information

No Of Bedrooms: 4

Facility Type: Residential

Last Occupied:

Permit issued by County: Yes

All plumbing fixtures enter septic system: Yes

Property Information Comments:

Inspection Date: 11/05/2025

Currently Occupied: Yes

System Installation Date: 05/02/2002

Permit Number: 012-02

County contacted for records: Yes

Primary Treatment

Tank 1

Tank Name: Tank 1

Tank Material: Concrete

No. of Compartments: 2

Type: Septic Tank

Tank Corrosion Type: Slight

Pump Tank Chamber: No

Tank Size (Gal): 2000

Liquid Level Type: Normal

Licensed Pumper Name: Rogers Septic

Date Pumped: 11/5/2025

Meets Setback to Well: N/A

Well Type:

Distance To Well (Ft.):

Is Accessible: Yes

Lid Intact: Yes

Risers Intact: No

Effluent Filter Present: Yes

Watertight: Yes

Tank/Vault Pumped: Yes

Inlet Baffle Present: Yes

Outlet Baffle Present: Yes

Functioning as Designed: Yes

Tank Comments:

General Primary Treatment Comments:

Water was slightly above flow line due to plugged filter. Pulled filter, cleaned, and put back in and water returned to flow line. THIS SYSTEM HAS AN EFFLUENT FILTER THAT NEEDS CLEANED ON REGULAR BASIS. Due to concrete lid being just beneath surface, cannot attach riser to this. Left the outlet pancake lid exposed.

Distribution Type

Distribution Box 1

Label: Distribution Box 1

Material Type: Plastic

Accessible: Yes

Box Opened: Yes

Baffle Present: Yes

Speed Levelers Present: Yes

Watertight: No

Functioning As Designed: No

General Distribution System Comments: Plastic distribution box is cracked/broken indicating the dbox is not watertight.

Would recommend replacing box.

Secondary Treatment

Lateral Field1

Distribution Type: Distribution Box

Lines: 6

Gallons Loaded: 200

Distance To Well (Ft.):

Grass Cover Present: Yes

Easement Present: N/A

Comments:

Material Type: Leaching Chamber

Total Length of Absorption Line: 600

Meets Setback to Well: N/A

Lateral Lines Probed: Yes

Lateral Lines Equal Length: Yes

Functioning as Designed: Yes

Trench Width: 24

System Hydraulic Loaded: Yes

Well Type:

Saturation or Ponding Present: No

System Located on Owner Property: Yes

General Secondary Treatment Comments:

Narrative Report

TOT Inspection Report Overall Narrative Comments: All wastewater goes to septic. 2000 gallon watertight concrete septic tank in working condition with slight deterioration. Accessible by center concrete lid to ground surface. Exposed inlet and outlet pancake lids, buried just beneath surface. Water was slightly above flow line due to plugged filter. Pulled filter, cleaned, and put back in and water returned to flow line. Inlet and outlet baffles present, outlet effluent filter present. 2 compartment tank. Ran camera out to find distribution box. Plastic distribution box is cracked/broken indicating the dbox is not watertight. Would recommend replacing box. Baffle and speed levelers present. Hydraulic load tested (via high water and house) 6x 100 equaling 600ft of 24" chambered laterals with 200 gallons. Each lateral took water and probed dry and clean. THIS SYSTEM HAS AN EFFLUENT FILTER THAT NEEDS CLEANED ON REGULAR BASIS. Due to concrete lid being

county's approval.	just beneath surface, cannot attach riser to this. Left the outlet pancake lid exposed. All recommendations are subject to county's approval.		
5/7075 2-52-25 PM	Page: 3 of d		



GOVERNOR KIM REYNOLDS LT. GOVERNOR CHRIS COURNOYER

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 18499 SETH BROWN CERT # 13190

Owner Name:

Crystal Venhaus

Address:

2626 160th St., Van Meter, IA 50261

County:

Madison

Inspection Date:

11/05/2025

Submitted Date:

11/5/2025

This page certifies a Time of Transfer inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).

