



Document 2026 GW3078

Book 2026 Page 3078 Pages 12

Date 10/15/2026 Time 9:10:03AM

Rec Amt \$ 00

BRANDY MACUMBER, COUNTY RECORDER
MADISON COUNTY IOWA

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED IN FULL BY TRANSFEROR

If the transaction is exempt from filing a declaration of value pursuant to Iowa Code 428A.1(2), **STOP HERE**. Pursuant to Iowa Code section 558.69(1), when no declaration of value is submitted during a transaction, you are not required to submit a groundwater hazard statement or include the statutory language in Iowa Code section 558.69(8A). Please consult your realtor or legal counsel for further advice, including on whether a declaration of value is required. The Department provides this information for statutory reference only.

Instructions for this document can be found at: <https://www.iowadnr.gov/media/5465>.

Attachment 1, if required, can be found at: <https://www.iowadnr.gov/media/5466>.

TRANSFEROR:

Name	Lucas Winebrenner			
Address	2885 235th Street	St Charles	IA	50240
	Number and Street or RR	City, Town or PO	State	Zip

TRANSFeree:

Name	Rachel Eller			
Address	223 W. Lane Street	Winterset	IA	50273
	Number and Street or RR	City, Town or PO	State	Zip

Address of Property Transferred:

2885 235th Street	St Charles	Iowa	50240
Number and Street or RR	City, Town or PO	State	Zip

Legal Description of Property: (Attach if necessary)

Parcel "E" located in the South Half (½) of the Northeast Quarter (¼) of Section Seven (7), in Township Seventy-five (75) North, Range Twenty-six (26) West of the 5th P.M., Madison County, Iowa, containing 15.715 acres, as shown in Amended Plat of Survey filed in Book 2002, Page 3899 on August 9, 2002, in the Office of the Recorder of Madison County, Iowa.

1. Wells (check one)

- ☒ No Condition - There are no known wells situated on this property.
- ☐ Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

- ☒ No Condition - There is no known solid waste disposal site on this property.
- ☐ Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in

Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- ☒ No Condition - There is no known hazardous waste on this property.
- ☐ Condition Present - There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- ☒ No Condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

- ☒ No Condition - There are no known private burial sites on this property.
- ☐ Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

- ☐ No Condition - All buildings on this property are served by a public or semi-public sewage disposal system.
- ☐ No Condition - This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
- ☒ Condition Present - There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #7]
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. This property is exempt from the private sewage disposal inspection requirements pursuant to the following Exemption [Note: for exemption #7 use prior check box]: _____
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The private sewage disposal system has been installed within the past two years pursuant to permit number: _____

Review the following two directions carefully:

- A. If you selected a box stating "No Condition" for every numbered section above, STOP HERE. Do not submit this form.** Instead, pursuant to Iowa Code section 558.69(8A), you must include the following language on the first page of the recorded deed, instrument, or other writing:

"There is no known private burial site, well, solid waste disposal site, underground storage tank, hazardous waste, or private sewage disposal system on the property as described in Iowa Code section 558.69, and therefore the transaction is exempt from the requirement to submit a groundwater hazard statement."


Please consult your realtor or legal counsel for further advice on this exemption. By law, the owner of the property is responsible for the accuracy of this statement, and the Department provides this information for statutory reference only.

- B. If you checked any box stating "Condition Present" for any of the numbered sections above, continue below.** You must complete this form, including providing all required information, and you must submit this form to the county recorder's office with declaration of value.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature:


(Transferor or Agent)

Telephone No.: (641) 330-2193

066-26
7-South



GOVERNOR KIM REYNOLDS
LT. GOVERNOR CHRIS COURNOYER
DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 23201 DREW HODGES CERT # 14481

Site Information

Parcel Description: **510090720015000**

Address: **2885 235th St., St. Charles, IA 50240**

County: **Madison**

Owner Information

Property is owned by a business: **No**

Business Name:

Owner Name: **Lucas Winebrenner**

Email Address: **lukewinebrenner@protonmail.com**

Address: **2885 235th St., St. Charles, IA 50240**

Phone No: **641-330-2193**

Site related information

No Of Bedrooms: **3**

Facility Type: **Residential**

Last Occupied: **03/01/2026**

Permit issued by County: **Yes**

All plumbing fixtures enter septic system: **Yes**

Property Information Comments:

Inspection Date: **09/03/2026**

Currently Occupied: **No**

System Installation Date: **09/11/2002**

Permit Number: **078-02**

County contacted for records: **Yes**

Primary Treatment

Tank 1

Tank Name: **Tank 1**

Tank Material: **Concrete**

No. of Compartments: **2**

Date Pumped: **9/3/2026**

Distance To Well (Ft.):

Risers Intact: **Yes**

Type: **Septic Tank**

Tank Corrosion Type: **Slight**

Pump Tank Chamber: **No**

Meets Setback to Well: **N/A**

Is Accessible: **Yes**

Effluent Filter Present: **Yes**

Tank Size (Gal): **2000**

Liquid Level Type: **Normal**

Licensed Pumper Name: **Rogers septic**

Well Type:

Lid Intact: **Yes**

Watertight: **Yes**

Tank/Vault Pumped: **Yes** Inlet Baffle Present: **Yes** Outlet Baffle Present: **Yes** Functioning as Designed: **Yes**
Tank Comments:

General Primary Treatment Comments:

Distribution Type

Distribution Box 1

Label: **Distribution Box 1** Material Type: **Plastic** Accessible: **Yes**
Box Opened: **Yes** Baffle Present: **Yes** Speed Levelers Present: **Yes**
Watertight: **Yes** Functioning As Designed: **Yes**

General Distribution System Comments :

Secondary Treatment

Lateral Field1

Distribution Type: **Distribution Box** Material Type: **Leaching Chamber** Trench Width: **24**
Lines: **4** Total Length of Absorption Line: **400** System Hydraulic Loaded: **Yes**
Gallons Loaded: **300** Meets Setback to Well: **N/A** Well Type:
Distance To Well (Ft.): Lateral Lines Probed: **Yes** Saturation or Ponding Present: **No**
Grass Cover Present: **Yes** Lateral Lines Equal Length: **Yes** System Located on Owner Property: **Yes**
Easement Present: **N/A** Functioning as Designed: **Yes**
Comments:

General Secondary Treatment Comments:

Narrative Report

TOT Inspection Report Overall Narrative Comments: **All wastewater goes to septic. 2000 gallon watertight concrete septic tank with moderate deterioration. Unable to probe through outlet wall. Accessible by lids and risers to ground surface. Two compartment tank. Inlet and outlet baffles present. Effluent filter present. Plastic D-box is watertight and in good working condition. Inlet baffles present. Speed levelers present. Hydraulic load tested (via house) 300 gallons to 4 x 100 equaling 400 of 24 inch chamber laterals. Each lateral took all water and probed dry/clean.**

TIME OF TRANSFER INSPECTION TOT# 23201 DREW HODGES CERT # 14481

Owner Name: **Lucas Winebrenner**

Address **2885 235th St. , St. Charles , IA 50240**


County: **Madison**

Inspection Date: **09/03/2026**

Submitted Date: **9/3/2026**


This page certifies a Time of Transfer inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).







Permit # 078-02 Carl + Amber Barr inspection 9/11/02



Permit No 078-02

Name: Carl & Amber Barr

Date of Inspection: 9/11/02

Inspected by: Elton A. Root

Contractor: Huff & Son

Dwelling under construction or moved in Yes ☒ No ☐

Setbacks

Meets required setbacks.

- Rural Water Yes ☒ No ☐
- Private wells/Groundwater heat pump bore holes/suction water lines/lakes
 - Outside required 50-foot setback for tank Yes ☒ No ☐
 - Outside required 100-foot setback for laterals Yes ☒ No ☐
- Streams/ponds (25-25 ft)-ditches (10-10 ft) Yes ☒ No ☐
- Indications of water lines under pressure Yes ☒ No ☐

Comments:

Building Sewer

- Clean outs – one right outside of house Yes ☒ No ☐
- location of cleanout inside house and set requirement
- Pipe is sch 40 and has a 4-inch diameter. Yes ☒ No ☐
- Grade – has adequate fall. Yes ☒ No ☐

Comments:

Tank

- Tank. Manufacture Lister Concrete ☒ Plastic ☐
- Capacity 2000 -gallon
- Two compartments, both meet the specs for capacity. Yes ☒ No ☐
- Baffle Yes ☒ No ☐
- Inlet/Outlet tees are ok. Yes ☒ No ☐
- Effluent filter in the outlet. Yes ☒ No ☐ Manuf. Zabel
- Tank depth. 12 inches
- Risers Yes ☐ No ☒
- Lids above grade screwed on Yes ☐ No ☐ Will be ☐

Comments:

Distribution Box

- Brand Tuf-Tite Other
- Bedded in cement. Yes ☒ No ☐ Will be ☐
- Has required inlet baffle. Yes ☒ No ☐ Will be ☐
- Outlet levels –are level. Yes ☒ No ☐ Unknown ☐

Comments:

Laterals

- Distribution lines: 4-inch PVC pipe – 35 SDR
- Distribution lines screwed to laterals. Yes ☐ No ☐ Will be ☐
- Lateral used. EQ24 Reduction? Yes ☐ No ☒
- Lateral depth 26" Perc depth 36 inches
- Laterals were level. Yes ☒ No ☐
- Adequate amount of undisturbed soil between laterals. Yes ☒ No ☐
- Distance 7 feet between laterals.

Comments:

Permit # 078-02 Carl & Amber Barr Inspection 9/11/02




Tank to House looking South

Looking NW from tank to lateral field



Lateral field looking east

Distribution lines looking South



Distribution Box with "T" baffle